

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088
NOV 19 1993

WELL API NO. 30-005-60778
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-6779
7. Lease Name or Unit Agreement Name Long Arroyo OD State Com
8. Well No. 1
9. Pool name or Wildcat Undesignated
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3473' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210
4. Well Location Unit Letter <u>I</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>14</u> Township <u>14S</u> Range <u>27E</u> NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3473' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Add perforations & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in and rigged up pulling unit. Set 1.81" check valve in packer at 7820'. Bled down tubing. Loaded with 2% KCL. Tested to 1000#, OK. Loaded annulus and tested to 500#, OK. Released on/off tool. Reversed tubing cap. Strip on BOP. TOOH with tubing. TIH with packer and RBP. Set RBP at 7790'. Pulled up. Stripped off BOP. Set packer at 7650'. Nippled up tree. Tested casing to 1000#. Swabbed tubing down. WIH w/1-11/16" Enerjet through tubing gun and perforated 7742-7744' with 12 .25" holes as follows: 7742, 43 & 7744'. Swabbed. Acidized perforations 7742-7744' with 1000 gallons 7-1/2% Morrow acid with 1000 scf/barrel nitrogen. Flow and swab back. Nippled up BOP. Released packer. Washed balls off RBP. Released RBP. Moved tools. Set RBP at 7695'. Tested to 1500#. Nippled down BOP. Installed tree. Set packer at 7470'. Tested casing to 1000#. Swabbed tubing down. WIH w/1-11/16" Enerjet through tubing gun and perforated 7587-7601' w/18 .25" holes as follows: 7587, 88, 89, 90, 97, 98, 99, 7600' and 7601'. Swabbed. Acidized perforations 7587-7601' w/2000 gallons 7-1/2% Morrow acid with 1000 scf/barrel nitrogen. Swabbed & flowed back. Released well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Nov. 15, 1993
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY M. Meyer TITLE M/S DATE NOV 23 1993