

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Ralph Nix ✓		8. Farm or Lease Name AL
3. Address of Operator P.O. Box 617, Artesia, New Mexico 88210		9. Well No. 1
4. Location of Well UNIT LETTER P 990 FEET FROM THE East LINE AND 990 FEET FROM THE South LINE, SECTION 24 TOWNSHIP 7-S RANGE 28-E NMPM.		10. Field and Pool, or Wildcat Wildcat SA
15. Elevation (Show whether DF, RT, GR, etc.) 4011' GR		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Squeeze cement <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/12/80 Went in hole. Prepare to squeeze perforations at 2582 to 86, 5 holes. Set cast iron bridge plug at 2618. Set squeeze tool at 2553. Squeeze perforations with 75 sx class C cement with 2½# of salt per sx. Latched into squeeze tool. Started pumping water. Got rate. Started mixing cement. Final squeeze pressure 3000#. Unlatched from squeeze tool and circulated out tubing. Shut well in preparing to perforate P-1 zone. Status of well - shut-in. WOC to set up and preparing to perforate.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ralph Nix TITLE Operations Manager DATE 11/18/80
APPROVED BY W.A. Gressett TITLE SURVEYOR, OIL & GAS, N.M. DATE NOV 21 1980
CONDITIONS OF APPROVAL, IF ANY: