

N.M.O.C.D. COPY

Form 9-331
(May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 16094

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hagerman Federal ~~State~~ Com

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Undesignated (San Andres)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 29, T-14-S, R-27-E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Southland Royalty Company

3. ADDRESS OF OPERATOR

1100 Wall Towers West; Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1980' FSL & 1780' FEL, Sec 29, T-14-S, R-27-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3434.6 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

REPAIRING WELL

☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rig up, install BOP. POOH w/tbg, GIH w/retainer and set at 1825'. Squeeze upper San Andres perfs with 75 sx Cl "C" cmt, pull out of retainer. Reverse excess cmt out of tbg and POOH. Leave 50' cmt on top of retainer. Run free point and determine depth of free 5 1/2" csg (approx 1000'). Cut off 5 1/2" csg above free point and pull csg. GIH w/tbg and load hole with 9-10 ppg salt mud. Spot a cmt plug 50' above and 50' below the 5 1/2" csg stub. POOH and leave a 15 sx plug at the surface. Rig down, clean location and install DHM.

This procedure is per Peter Chester, USGS, Roswell, New Mexico 2/18/81

RECEIVED
MAR 25 1981

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE District Operations Engineer

DATE 3-23-81

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

MAR 25 1981

JAMES A. GILLHAM
DISTRICT SUPERVISOR

See Instructions on Reverse Side