

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED BY
FEB 07 1986
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. 30-005-619807

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒

GAS WELL ☐

OTHER-

1. Name of Operator

RHYMES DRILLING COMPANY, INC

2. Address of Operator

P O BOX 729, ROSWELL, NEW MEXICO 88201

3. Location of Well

UNIT LETTER L 1650 FEET FROM THE SOUTH LINE AND 660 FEET FROM
THE WEST LINE, SECTION 6 TOWNSHIP 8N RANGE 29E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

O'BRIEN-DEMING "6"

9. Well No.

#1

10. Field and Pool, or Wildcat

BULLSEYE-SAN ANDRES

15. Elevation (Show whether DF, RT, GR, etc.)

4026.3⁺ GL 4027.7

12. County

CHAVES

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNT. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

01/25/86 - Ran 2603' tbg. Pumped H2O to clear tbg. Mix and pump 25 sks cl "c" w/ 4% ca cl and displace. Wait 1 1/2 hours. Ran in w/ tbg, did not tag. Set second plug at 2603' w/ 25 sks cl "c" 4% ca cl and displace. Pull up and wait 1 1/2 hours. Ran in w/ tbg and tag cement at 2543'. Circ hole w/ nacl gel. Pull tbg to 2200' and pump 25 sks cl "c" w/ 2% ca cl. Displace w/ na cl gel. Lay down tbg and trip in and perf at 1550'. Set packer at 1252' and pump 45 sks cl "c" w/ 4% ca cl. Displace w/ na cl gel. TO w/ tbg. Trip in and tag cement at 1364'. Perf at 175'. Run 1 jt tbg and pack off. Circ thru tbg and out back side to surface w/ brine water. Pump 85 sks cl "c" w/ 2% ca cl and circ to surface.

01/29/86 - Set dry hole marker and clear location.

Post ID-2
2-14-86
PFA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J L Pinn

TITLE Clerk

DATE 02/05/86

APPROVED BY Danell Moore

TITLE Geologist

DATE 8/10/87

CONDITIONS OF APPROVAL, IF ANY: