

☐ Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-005-62372
5. Indicate Type of Lease
STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
LG-5565

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator
McKAY OIL CORPORATION

3. Address of Operator
PO BOX 2014, ROSWELL NM 88202-2014

4. Well Location

Unit Letter I : 1980 feet from the SOUTH line and 660 feet from the EAST line

Section 33 Township 5S Range 22E NMPM CHAVES County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4106' GL

7. Lease Name or Unit Agreement Name:
INEXCO STATE

8. Well No.
7

9. Pool name or Wildcat
PECOS SLOPE ABO (WEST)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

This well was plugged & abandoned in March 1999 as follows:

2/24/1999 Notify OCD. MIRU - Nipple down wellhead - NU BOP - lay down 92 jts 2 3/8" tbg - set CIBP @ 2821' - load hole - pressure test csg to 500# for 30 minutes - SION.
3/01/1999 Notify OCD. MIRU - Dump 5 sxs on top of CIBP - load hole w/mud - cut csg @ 1533' - lay down 8 jts. SION.
3/02/1999 Lay down csg - RIH w/tbg & spot 25 sxs @ 1572' - POOH - WOC-tag plug @ 1468' - POOH & spot 50 sxs @ 965' - POOH - WOC - Tag plug @ 848' - POOH & spot 30 sxs @ 100' to surface - cut off wellhead. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tricia Moore TITLE PRODUCTION ANALYST DATE 01/09/2002

Type or print name TRICIA MOORE

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep ID DATE MAR 15 2002

Conditions of approval, if any

Telephone No. 505.623.4735