Submit 3 Copies To Appropriate District Office	State of Nev	v Mexico	· · · · · · · · · · · · · · · · · · ·	Form C-103
District 1 Energy, Minerals and Natural Resources			Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II	OIL CONSERVAT	YON DIVISION	30-005-62566	
811 South First, Artesia, NM 88210 District III	1220 South St.		5. Indicate Type of	of Lease
1000 Rio Brazos Rd., Aztec, NM 87410			- · · · -	X FEE
District IV	Santa Fe, N	M 8/303	6. State Oil & G	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			LG-4927	
	CES AND REPORTS ON W		7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A		8
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR PERMIT" (FORM C-	101) FOR SUCH	Dragonfly ARX	X State
1. Type of Well:		12 13 9 10 C	=:=g=:,	
Oil Well Gas Well X	Other	9		
2. Name of Operator	June 7	→	7. Well No.	
Yates Petroleum Corpor	ration		#1	
3. Address of Operator	dion		8. Pool name or	VV:144
_	ia, NM 88210	RECEIVED		
100 3. 4" 311661 Affes	14, 19/91 00210	OCD - ARTESIA	Pecos Slop	De Abo
4. Well Location				
Essanon				
Unit Letter D : 6	60 feet from the No	orth line and 990	feet from the	West line
	1001 110111 1110	770	icet from the _	Wesi inte
Section 30	Township 98 Rang	ge 27E N	IMPM Chaves	County
	10. Elevation (Show wheth			County
		310.5' GR		
11 Check A	ppropriate Box to Indica		Report or Other	Data
NOTICE OF IN	TENTION TO:		BSEQUENT REF	
		30	DOEQUENT REI	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WO	PRK	ALTERING CASING X
TEMPORARII V ARANDON	CHANGE PLANS	7 0014151105.5		PLUG AND
		COMMENCED		,
TEMPORARILY ABANDON	OTATOL I LAND		RILLING OPNS.	ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST		ABANDONMENT
	<u> </u>			ABANDONMENT
	MULTIPLE	CASING TEST	AND	
PULL OR ALTER CASING OTHER:	MULTIPLE COMPLETION	CASING TEST CEMENT JOB OTHER: Recor	AND mpletion – Perforate, a	cidize and frac X
PULL OR ALTER CASING OTHER: Describe proposed or completed op	MULTIPLE COMPLETION [CASING TEST CEMENT JOB OTHER: Recor	AND mpletion – Perforate, a	cidize and frac X
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE F	MULTIPLE COMPLETION [CASING TEST CEMENT JOB OTHER: Recor	AND mpletion – Perforate, a	cidize and frac X
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation.	MULTIPLE COMPLETION Perations. (Clearly state all perations). For Multiple Co	CASING TEST CEMENT JOB OTHER: Recor	AND mpletion – Perforate, a	cidize and frac X
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up posed with the second starting and rig up posed work.	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Co	CASING TEST CEMENT JOB OTHER: Record criment details, and given pletions: Attach well	mpletion – Perforate, a e pertinent dates, inclu lbore diagram of prop	cidize and frac X
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up proposed work or completed out cement are selected.	MULTIPLE COMPLETION Deterations. (Clearly state all per RULE 1103. For Multiple Co culling unit. and CIBP at 5950'. Pushed	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well considered to PBTD at 62	mpletion – Perforate, a e pertinent dates, incluibore diagram of prop	cidize and frac X Iding estimated date of osed completion or
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement ar 4/6/01 – Set cement retainer of	MULTIPLE COMPLETION Deterations. (Clearly state all per RULE 1103. For Multiple Co culling unit. and CIBP at 5950'. Pushed	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well considered to PBTD at 62	mpletion – Perforate, a e pertinent dates, incluibore diagram of prop	cidize and frac X Iding estimated date of osed completion or
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement ar 4/6/01 – Set cement retainer of at 2600 psi.	MULTIPLE COMPLETION Derations. (Clearly state all perations.) RULE 1103. For Multiple Control Ulling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordon	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well considered to PBTD at 62 prician perfs 5999-60.	and appletion – Perforate, and the pertinent dates, included by the performance of properties of the performance of the perforate, and the perforate of the perforation of the perforate of the	cidize and frac X Iding estimated date of osed completion or
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement ar 4/6/01 – Set cement retainer of at 2600 psi. 4/9/01 – Perforate Penn sand	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Co culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordov 5875-5884', 54 holes and	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well considered to PBTD at 62 vician perfs 5999-60. 5966-5976', 60 hole	mpletion – Perforate, a e pertinent dates, included bore diagram of propertion (270). 26' with 100 sxs H +	acidize and frac X uding estimated date of osed completion or 4% FL. Squeeze off
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up pour 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 1	MULTIPLE COMPLETION Deterations. (Clearly state all per RULE 1103. For Multiple Co culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordox 5875-5884', 54 holes and	CASING TEST CEMENT JOB OTHER: Record critinent details, and given impletions: Attach well countries and perfs 5999-60. 5966-5976', 60 hole cidize perfs 5875-58	mpletion – Perforate, a e pertinent dates, incluibore diagram of prop 270'. 26' with 100 sxs H + es, .42".	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL.
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up pour 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Pour Set CIBP at 5850'.	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Co culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordov 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A perforate Wolfcamp 5520	CASING TEST. CEMENT JOB OTHER: Record retrinent details, and given pletions: Attach well at CIBP to PBTD at 62 rician perfs 5999-60. 5966-5976', 60 hole cidize perfs 5875-58-5528', 9 holes, 5534	mpletion – Perforate, a e pertinent dates, included by the last of properties of properties of properties of the last of the l	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL.
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement ar 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Possible 1865-1860'. Possible 1865-1	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Control of the state of the st	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well concerns the concerns of the concerns	mpletion – Perforate, a e pertinent dates, included by the last of properties of properties of properties of the last of the l	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL.
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Por 5582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp properties.	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Co culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordox 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 perfs 5520-5668' with 3006	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well countries and perfs 5999-60. 5966-5976', 60 hole cidize perfs 5875-58-5528', 9 holes, 553468', 21 holes. Total of gals 20% IC HCL.	mpletion – Perforate, a e pertinent dates, included libore diagram of propertinent dates, included libore diagram of propertine diag	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL.
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement ar 4/6/01 – Set cement retainer of at 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Por 5582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp por 4/23/01 – Put 35' cement on 0	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Co culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordox 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 perfs 5520-5668' with 3006 CIBP at 5850'. Set CIBP at	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well countries and perfect for the perfect of the perfect	mpletion – Perforate, a e pertinent dates, includent date	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL.
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up pour 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Pour 5582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp pour 4/23/01 – Put 35' cement on Cement at 5800'.	MULTIPLE COMPLETION Deterations. (Clearly state all per RULE 1103. For Multiple Coulling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordox 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 perfs 5520-5668' with 3000 CIBP at 5850'. Set CIBP at 5030', .42" holes. Set cer	CASING TEST, CEMENT JOB OTHER: Record retrinent details, and given performs: Attach well at CIBP to PBTD at 62 rician perfs 5999-60. 5966-5976', 60 hole cidize perfs 5875-58-5528', 9 holes, 553-68', 21 holes. Total of gals 20% IC HCL. It 5230', cap with 35 ment retainer at 500 performs.	mpletion – Perforate, a e pertinent dates, incluibore diagram of properties with 100 sxs H + es, .42". 384' with 1000 gals 4-5540', 7 holes, 55 of 104 holes, .42".	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL.
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up pour 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Pour 5582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp pour 4/23/01 – Put 35' cement on Cement at 54/24/01 – Pump 100 sxs H + .49	MULTIPLE COMPLETION Deterations. (Clearly state all per RULE 1103. For Multiple Coulling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordox 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 perfs 5520-5668' with 3000 CIBP at 5850'. Set CIBP at 5030', .42" holes. Set cer	CASING TEST, CEMENT JOB OTHER: Record retrinent details, and given performs: Attach well at CIBP to PBTD at 62 rician perfs 5999-60. 5966-5976', 60 hole cidize perfs 5875-58-5528', 9 holes, 553-68', 21 holes. Total of gals 20% IC HCL. It 5230', cap with 35 ment retainer at 500 performs.	mpletion – Perforate, a e pertinent dates, incluibore diagram of properties with 100 sxs H + es, .42". 384' with 1000 gals 4-5540', 7 holes, 55 of 104 holes, .42".	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL.
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Possible 2582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp por 4/23/01 – Put 35' cement on Competence at squeeze holes at 54/24/01 – Pump 100 sxs H + .49 See attached	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Con culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordox 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 berfs 5520-5668' with 3006 CIBP at 5850'. Set CIBP at 5030', .42" holes. Set cer 6 FL and 100 sxs H neat of	CASING TEST CEMENT JOB OTHER: Record critinent details, and given impletions: Attach well in CIBP to PBTD at 62 prician perfs 5999-60 perfs 5875-58 perfs 5875-58 perfs 5875-58 perfs 5830	mpletion – Perforate, a e pertinent dates, included libore diagram of properties. A 200'. 270'. 26' with 100 sxs H + 28, .42''. 384' with 1000 gals 4-5540', 7 holes, .55 of 104 holes, .42''. 5' cement. 10'. off at 3000 psi.	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL.
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up pour 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Pour 5582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp pour 4/23/01 – Put 35' cement on Cement at 54/24/01 – Pump 100 sxs H + .49	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Control of Section 1986). Squeeze Ordon 19875-5884', 54 holes and 1998 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 perfs 5520-5668' with 3000 CIBP at 5850'. Set CIBP at 5850'. Set CIBP at 5850', 32' holes. Set cer 67 FL and 100 sxs H neat above is true and complete the section 1988 for the section 1988	CASING TEST CEMENT JOB OTHER: Record critinent details, and given impletions: Attach well at CIBP to PBTD at 62 prician perfs 5999-60 perfs 5875-58 perfs 5875-58 perfs 5875-58 perfs 580 perfs 5875-58 perfs 580 perfs 5875-58 perfs 5830 perfs	mpletion – Perforate, a e pertinent dates, included libore diagram of properties. A2". 26' with 100 sxs H + es, .42". 384' with 1000 gals 4-5540', 7 holes, .55 of 104 holes, .42". 5' cement. 10'. of at 3000 psi. edge and belief.	acidize and frac X ading estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL. 50-5570', 21 holes,
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Por 5582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp properties and 18/01 – Put 35' cement on Complete Perforate 4 squeeze holes at 54/24/01 – Pump 100 sxs H + .49 See attached Thereby certify that the information	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Control of Section 1986). Squeeze Ordon 19875-5884', 54 holes and 1998 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 perfs 5520-5668' with 3000 CIBP at 5850'. Set CIBP at 5850'. Set CIBP at 5850', 32' holes. Set cer 67 FL and 100 sxs H neat above is true and complete the section 1988 for the section 1988	CASING TEST CEMENT JOB OTHER: Record critinent details, and given impletions: Attach well at CIBP to PBTD at 62 prician perfs 5999-60 perfs 5875-58 perfs 5875-58 perfs 5875-58 perfs 580 perfs 5875-58 perfs 580 perfs 5875-58 perfs 5830 perfs	mpletion – Perforate, a e pertinent dates, included libore diagram of properties. A2". 26' with 100 sxs H + es, .42". 384' with 1000 gals 4-5540', 7 holes, .55 of 104 holes, .42". 5' cement. 10'. of at 3000 psi. edge and belief.	acidize and frac X ading estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL. 50-5570', 21 holes,
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Possible 2582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp por 4/23/01 – Put 35' cement on Competence at squeeze holes at 54/24/01 – Pump 100 sxs H + .49 See attached	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Control of Section 1986). Squeeze Ordon 19875-5884', 54 holes and 1998 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 perfs 5520-5668' with 3000 CIBP at 5850'. Set CIBP at 5850'. Set CIBP at 5850', 32' holes. Set cer 67 FL and 100 sxs H neat above is true and complete the section 1988 for the section 1988	CASING TEST CEMENT JOB OTHER: Record critinent details, and given impletions: Attach well in CIBP to PBTD at 62 prician perfs 5999-60 perfs 5875-58 perfs 5875-58 perfs 5875-58 perfs 5830	mpletion – Perforate, a e pertinent dates, included libore diagram of properties. A2". 26' with 100 sxs H + es, .42". 384' with 1000 gals 4-5540', 7 holes, .55 of 104 holes, .42". 5' cement. 10'. of at 3000 psi. edge and belief.	acidize and frac X ading estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL. 50-5570', 21 holes,
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up por 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Por 5582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp properties and 18/01 – Put 35' cement on Complete Perforate 4 squeeze holes at 54/24/01 – Pump 100 sxs H + .49 See attached Thereby certify that the information	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Con Culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordow 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A perforate Wolfcamp 5520 8', 25 holes and 5648-56 perfs 5520-5668' with 3006 CIBP at 5850'. Set CIBP at 5030', .42" holes. Set cer 6 FL and 100 sxs H neat con above is true and complete to	CASING TEST CEMENT JOB OTHER: Record critinent details, and given impletions: Attach well at CIBP to PBTD at 62 prician perfs 5999-60 perfs 5875-58 perfs 5875-58 perfs 5875-58 perfs 580 perfs 5875-58 perfs 580 perfs 5875-58 perfs 5830 perfs	mpletion – Perforate, a e pertinent dates, included libore diagram of properties. A constant of the properties of the pr	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL. 50-5570', 21 holes,
PULL OR ALTER CASING OTHER: Describe proposed or completed op starting any proposed work). SEE Frecompilation. 4/4/01 – Move in and rig up pour 4/5/01 – Drilled out cement are 4/6/01 – Set cement retainer of 2600 psi. 4/9/01 – Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 – Set CIBP at 5850'. Pour 5582-5602', 21 holes, 5614-563 4/18/01 – Acidize Wolfcamp pour 4/23/01 – Put 35' cement on Competence at squeeze holes at 54/24/01 – Pump 100 sxs H + .49 See attached I hereby certify that the information SIGNATURE Type or print name Susan Here	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Con Culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordow 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A Derforate Wolfcamp 5520 8', 25 holes and 5648-56 Derfs 5520-5668' with 3006 CIBP at 5850'. Set CIBP at 5030', .42" holes. Set cer 6 FL and 100 sxs H neat at above is true and complete to TITLE	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well countries and perfect the second perfect of	mpletion – Perforate, a e pertinent dates, included libore diagram of properties. A constant of the properties of the pr	acidize and frac X ading estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL. 50-5570', 21 holes,
PULL OR ALTER CASING OTHER: Describe proposed or completed opstarting any proposed work). SEE Frecompilation. 4/4/01 - Move in and rig up pour 4/5/01 - Drilled out cement are 4/6/01 - Set cement retainer of 2600 psi. 4/9/01 - Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 - Set CIBP at 5850'. Pour 5582-5602', 21 holes, 5614-563 4/18/01 - Acidize Wolfcamp pour 4/23/01 - Put 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize P	MULTIPLE COMPLETION Deterations. (Clearly state all per RULE 1103. For Multiple Control of September 1950). Pushed at 5986'. Squeeze Ordown 1960 gals 7.5% IC HCL. At 1960 ga	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well at CIBP to PBTD at 62 prician perfs 5999-60; 5966-5976', 60 hole cidize perfs 5875-58-5528', 9 holes, 553468', 21 holes. Total or gals 20% IC HCL. at 5230', cap with 35 ment retainer at 500 perfs. Squeeze or the best of my knowledge to the best of	mpletion – Perforate, a e pertinent dates, included libore diagram of properties. A constant of the properties of the pr	acidize and frac X ading estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL. 50-5570', 21 holes,
PULL OR ALTER CASING OTHER: Describe proposed or completed opstarting any proposed work). SEE Frecompilation. 4/4/01 - Move in and rig up pour 4/5/01 - Drilled out cement are 4/6/01 - Set cement retainer of 2600 psi. 4/9/01 - Perforate Penn sand Acidize perfs 5966-5976' with 14/17/01 - Set CIBP at 5850'. Pour 5582-5602', 21 holes, 5614-563 4/18/01 - Acidize Wolfcamp pour 4/23/01 - Put 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize Wolfcamp pour 35' cement on Complete Penn sand Acidize P	MULTIPLE COMPLETION Derations. (Clearly state all per RULE 1103. For Multiple Con Culling unit. and CIBP at 5950'. Pushed at 5986'. Squeeze Ordow 5875-5884', 54 holes and 1000 gals 7.5% IC HCL. A Derforate Wolfcamp 5520 8', 25 holes and 5648-56 Derfs 5520-5668' with 3006 CIBP at 5850'. Set CIBP at 5030', .42" holes. Set cer 6 FL and 100 sxs H neat at above is true and complete to TITLE	CASING TEST CEMENT JOB OTHER: Record critinent details, and given pletions: Attach well at CIBP to PBTD at 62 prician perfs 5999-60; 5966-5976', 60 hole cidize perfs 5875-58-5528', 9 holes, 553468', 21 holes. Total or gals 20% IC HCL. at 5230', cap with 35 ment retainer at 500 perfs. Squeeze or the best of my knowledge to the best of	mpletion – Perforate, a e pertinent dates, included libore diagram of properties. A constant of the properties of the pr	acidize and frac X Iding estimated date of osed completion or 4% FL. Squeeze off 7.5% IC HCL. 50-5570', 21 holes,