

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other instr
verso side)WILDCAT
10-00 70Form approved.
Budget Bureau No. 43-21434

1. LEASE DESIGNATION AND SERIAL NO.

NM-068043

2. IF INDIAN, ALLOTTEE OR TRUST LAND

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☐ WELL GAS ☐ WELL OTHER ☒ Water Well

2. NAME OF OPERATOR

Read & Stevens, Inc. ✓

3. ADDRESS OF OPERATOR

P.O. Box 2126, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FNL & 1650' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, HY, OR, etc.)

3588.5 GR

12. COUNTY OR PARISH

Chaves

13. STATE

N.Mex.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENTS*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

4/14/72

This well was previously drilled to a TD of 316' and subsequently an attempt was made to convert the test to a fresh water supply well. The well was cleaned out to 260'. Two sacks of cement were set @ 260'. New PBTD was 252'. Perf 2 SPF 220' to 235'. No fluid. Treated with 500 gal 15% acid. Well tested 14 gals per min. While testing well turned to salt water - 140,000 PPM Chlorides. Set 35 sk cement plug 252'-200'. Fill hole with good mud. Set 10 sk cement plug 10'-0'. Weld on 1/4" metal plate on top of 12-3/4". Install dry hole marker.

Location is ready for Inspection.

RECEIVED
APR 18 1972
U.S. GEOLOGICAL SURVEY
ARTESIAN

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

4/17/72

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side