

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-005-62988	
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name State A-6	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐		8. Well No. 1	
2. Name of Operator L. Cleo Thompson		9. Pool name or Wildcat W/C Ellenberger	
3. Address of Operator 325 North St. Paul Suite 4500 Dallas Tx. 75201			
4. Well Location Unit Letter <u>B</u> : <u>950</u> Feet From The <u>N</u> Line and <u>2180</u> Feet From The <u>E</u> Line Section <u>6</u> Township <u>16S</u> Range <u>17E</u> NMPM Chaves County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-13-94 PSA
 Reached T.D. @ 3999' Circulate hole with stiff foam for 1 1/2 hrs.
 Pulled 2 stands and drill string stuck. Unable to pull loose, Pumped 500 bbs gel water and pull 160,000 lbs, still stuck. worked with it about 14 hrs. Unable to pull free. Call Rotary Wireline Service to indicate free point. Run wire line in hole free point indicated @ 3650' P.O.H. with wireline, go in hole with String Shot and back off 6" drill collars @ 3650'. Left 4 D.C. and bit in hole. Come out of hole Lay D.C. down. Go back in hole. with open end drill pipe. Plugging as follows.
 1. Plug-80 sx. Class C Lmt. @ 3650' and tie back to 3410'- Bliss, Ellenberger and Montoya
 2. Plug @ 3150' Mississippi 45 sx
 3. Plug @ 2290' Abo 45 sx.
 4. Plug @ 1770' Tubb 45 sx.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Amador Pando Jr. TITLE Production Manager DATE 10-25-94
 TYPE OR PRINT NAME Amador Pando Jr. TELEPHONE NO. 677-2396

(This space for State Use)

APPROVED BY SUPERVISOR, DISTRICT II TITLE DATE DEC 8 1994

CONDITIONS OF APPROVAL, IF ANY:

5. Plug @ 1300' Shoe plug 80 sx. Tag @ 1400'

6. Plug @ 1300' 49 sx. Tag @ 1190'

7. Plug @ Surface 25 sx. (circulated)

Well P.8A.