



mit 3 copies to Appropriate District Office	State of Energy, Minerals and Na	New Mexico tural Resources De	partment	C157 Form C-103 Revised 1-1-89
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III	OIL CONSERVAT P.O. Box Santa Fe, New Mexico	2088	N	WELL API NO. 30-015-01372 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410				B-8617
(DO NOT USE THIS FORM FOR DIFFERENT R	RY NOTICES AND REPOR REPORT FOR TO DRILL OR TO RESERVOIR. USE "APPLICATIO RM C-101) FOR SUCH PROPOSA OTHER	DEEPEN OR PLUG BA	ACK TO A	7. Lease Name or Unit Agreement Name Spurck F State
2. Name of Operator	OTHER			8. Well No.
Yates Drilling Company 3. Address of Operator 105 South 4 th Street, Artesia, NM 88210 4. Well Location				2 9. Pool name or Wildcat Red Lake, Qn, Grb
Unit LetterF:2310	Feet From The <u>North</u>		2310	Feet From The <u>West</u> Line
Section 15	Township 17S	and Range 28E	NMPM	Eddy County
11. Ch	eck Appropriate Box to Indi	cate Nature of Noti	ce Report o	r Other Data
NOTICE OF I	NTENTION TO:			NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔀	REMEDIAL WO	-	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS	. DPLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST A	ND CEMENT J	OB
OTHER:	[] 	OTHER:		
12. Describe Proposed or Completed Operations work) SEE RULE 1103.	(Clearly state all pertinent details, a	and give pertinent dates,	including estim	nated date of starting any proposed

See attachment



* Notifie N.M. O. C. D. -> winness Flagging Operations .

I hereby certify that the information above is true and comp SIGNATURE Kayen & Leishman	Diete to the best of my knowledge and belief.	DATE	2-12-01
TYPE OR PRINT NAME [/] Karen J. Leishman			TELEPHONE NO.505-746-0308
(This space for State Use)			
APPROVED BY Mike Stublifield	TITLE Field Rip. II	DATE	2/27/01

CONDITIONS OF APPROVAL, IF ANY:

Spurck F State 002 2310' FNL & 2310 FWL F-15-17S-28E Eddy, NM 30-015-01372

Proposed Plug and Abandonment Procedure

- 1) Clear and level location.
- 2) Check anchors and replace as necessary.
- 3) Rig up workover unit.
- 4) Pull rods, pump and tubing out of hole.
- 5) Inspect tubing.
- 6) Pick up rental tubing if necessary.
- 7) RIH w/ CIBP and set at +/- 1906' (50' above top perforation).

596

- 8) Circulate hole w/10 ppg mud.
- 9) Spot 100' cement plug on top of CIBP (1806' 1906').
- 10) Spot 100' Cement plug across top of Queen (1190' 1290') Min. cmi Plug 2538.

11) POH with tubing.

- 12) Cut and pull 5 $\frac{1}{2}$ casing at $\frac{1}{510^2}$.
- 13) RIH w/ tubing and spot cement plug from 560' to 360'.
- 14) POH w/ tubing.
- 15) WOC
- 16) RIH and tag cement.
- 17) Spot additional cement as necessary.
- 18) Spot cement plug from 0 to 100'.
- 19) Erect regulation dry hole marker.
- 20) Remove all equipment from location.