

RECEIVED
OCT 10 1991

O. C. D.
ARTESIA OFFICE

6. Perforate squeeze holes at 2150'. TIH with CICR and set at 1950'. Open annulus valve and squeeze cement with 55 sx Cl H. Do not displace below CICR. POH.
7. Perforate squeeze holes at 1400'. TIH with CICR and set at 1200'. Squeeze cement with 55 sx Cl H. Do not displace below CICR. POH.
8. Perforate squeeze holes at 900'. Close blind rams and attempt to break circulation to surface. RD BOP and NU cementing head on 5-1/2" casing. Pump 240 sx Cl C down 5-1/2" casing and out annulus. Do not displace cement.
9. Cut off casing and wellhead. Weld on abandonment plate. Install dry hole marker.
10. Clean up location and reclaim working pit.