

7. TIH w/ retrievable packer on 2-7/8" workstring to 6050'. Spot 100 gals 15% NEFE HCl acid across Abo perms 6024'-50'. TOH, reverse 5 bbls and set packer @ 5924'. Pressure annulus to 500 psi.
8. Acidize Abo 6024'-50' w/ 4000 gals NEFE HCL acid @ 1-2 BPM dropping 90- 1.3 SG ball sealers in sets of 3, evenly spaced throughout. Maximum pressure: 1500 psi. Flush to bottom perf w/ formation water. SI for 30 min.
9. Flow/swab back load and evaluate w/ Engineering.
10. Release packer. TOH, laying down 2-7/8" workstring. Test in hole w/ CA to 4000# below slips as per production department specifications. ND BOP. NU WH. RD PU. Clean location. Release rig. TOPS.  
*Set pack above squeeze perms.*

*L. M. Thompson*  
L. M. Thompson

Approval:

*R. D. Reynolds*  
R. D. Reynolds

*J. E. Shields*  
J. E. Shields