STATE OF NEW MEXICO	
THEREY AND MINERALS DEPARTMENT	\$1.5 ¹
OIL CONSERVATION OIVISIO	5. Jon 10. 200
DISTRIBUTION P. O. BOX 2088	Form C-103 Revised 10-1-3
SANTA FE, NEW MEXICO 8750 MAY 9 1 1000	
SANTAFE SANTAFE SANTAFE, NEW MEXICO 8750 MAY 31 1983	5a. Indicate Type of Leane
	State X Fee
OPERATOR O. C. D.	5. State Otl & Gas Leose No.
ARTESIA, OFFICE	E5131
SUNDRY NOTICES AND REPORTS ON WELLS (00 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
WELL OTHER- Water Injection	East Henshaw
, crime of Operator	8. Farm or Lease Name
Stamford Natural Resources Group 1980-1 $$	Tract 16
Address of Operator	9. Well No.
c/o S&J Operating Co., P. O. Box 2249, Wichita Falls, TX 76307	5
Location of Well 3200	10. Field and Pool, or Wildcat
UNIT LETTER P 3330 FEET FROM THE S LINE AND 660 FEET FROM	West Henshaw Grayburg
THE E LINE, SECTION 2 TOWNSHIP 16S RANGE 30E	
TAL RANGE NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3937' DF	Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Othe	
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
CUPOPAR HLY ABANDON	PLUG AND ABANDONMENT X
CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	[]
OTHER	L_J
Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including a	

. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On or about 1/28/83, a recommended procedure for plugging this well was given S & J Operating Company by Mike Williams of the Oil Conservation Division. The following is a description of the work performed on 5/11/83:

Berry's Well Service moved in & rigged up 5/10/83. Geosources Wireline Service got stuck on county road in sand & was 1 hr. late. Geosources Wireline Service made 3 dump bailer runs with cement & left 42'+ of cement on top of RBP @2600'. Geosources perforated well @1700', 2SPF, 1', & 1100', 2SPF, 1'. Ran $2\frac{1}{2}$ " Watson Tension Packer & 48 jts of $1\frac{1}{2}$ " IJ tubing to 1481.40'. Set packer. Pumped 40 sack plug @1700' - 100' plug outside casing & 100' plug inside casing. Waiting on cement. Tag plug (108') @1592'. Pulled 20 jts. -28 jts. in the hole. Set packer @873'. Pumped 40 sack plug @1100' - 100' plug outside casing & 100' plug inside casing. Waiting on cement. Tag cement (117') @983'. Pulled 28 jts. tubing & packer. Tied onto 2 7/8" casing. Pumped 45 sacks into hole @300'. Left casing full of cement to surface.

AIGNED Sed H. Amith, P.	ete to the best of my knowledge and belief.	DATE 5/26/83
ANDIVED BY BALLY BLOCK	me_ Alcologest	DATE 3-14-84