Form 9-331 (May 1963)

WELL X

16.

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

WELL

TEXACO Inc.

OTHER

UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT	RIPL	CA7	Ė
(Other Inst	ructions	OIL.	re
verse side)		2	

	Form approved.
	Budget Bureau No. 42-R142
_	I PLOD DEGLES AND

GEO	OCICAL	SHRVEY

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

At surface

P. O. Box 728 - Hobbs, New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

NM-08529 C. IF INDIAN, ALLOTTEE OR TRIBE NAME (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) None 7. UNIT AGREEMENT NAME Square Lake "31" Unit 8. FARM OR LEASE NAME Square Lake "31" Unit 9. WELL NO. 10. FIELD AND POOL, OR WILDCAT

Square Lake

N.M.

Well located 660' for Line of Section 31,	rom the West Line and 660' from the South T-16-S, R-30-E, Eddy County, New Mexico	SQUATE LAKE 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether Dr. RT, GR, etc.)	Sec. 31, T-16-S, R-30-E
Regular	3698' (GR)	Eddy N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

				· · ·		
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:				
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	7
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CABING	
SHOOT OR ACIDIZE	<u>x</u>	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		(Other)		
(Other)				(Note: Report results of m Completion or Recompletion	ultiple completion on Well Report and Log form.)	-

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)

We propose to do the following work on subject well:

- Treat down tubing-casing annulus with 300 gallons Gypsol scale remover.
- Shut in flow line and circulate well for 24 hours.
- Produce well for 24 hours.
- Acidize with 500 gallons 7-1/2% acid.
- Produce well for 24 hours.
- Tag bottom of hole with tubing & pull tubing to check fillup.
- Dump sufficient pea gravel down casing to fill hole to lowest perforation. 7.
- Pack well by dumping 125 lb. of Nocor 815 phosphate pellets down casing.
- Swab well, recover load oil, test, and return well to production.

RECEIVED

RECEIVED
DEC 23 1965 J. S. GEOLOGICA ARTESHA HEA

18. I hereby certify that the foregoing is true and corr SIGNED Dan Crizett	Assistant	DATE December 22, 196
APPROVED BY	TITLE	DATE
AP 23		

*See Instructions on Reverse Side