NO. OF COPIES RECEIVED 3	L			Form C-103
DISTRIBUTION				Supersedes Old C-102 and C-103
SANTAFE	NEW MEXIC	O OIL CONSERVATION COMMISSION	VED	Effective 1-1-65
FILE		REULI	• •••	······
U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE		AUG 1 9 1	1974	State XX Fee
OPERATOR		1100		S. State Oil & Gas Lease No. NM B-3006
			C.	
DO NOT USE THIS FORM	UNDRY NOTICES AND RE	PORTS ON WELLS	FIGE	
1.	PPEICATION FOR PERMIT (FORM C	C-101) FOR SUCH PROPOSALS.)		7. Unit Agreement Name
OIL XX GAS WELL	OTHER-			Square Lake
2. Name of Operator				8. Farm or Lease Name
Newmont Oil Company 🗸				Overton
3. Address of Operator				9. Well No.
P.0. Box 1305, Ar	tesia, New Mexico 88	3210 m		9
4. Location of Well	1000			10. Field and Pool, or Wildcat
UNIT LETTER	1980 	South LINE AND	_ FEET FROM	Square Lake G. SA
_		_		
East Line	, SECTION TOWNS	SHIP 16 S RANGE 30 E	Е имрм.	<i>AIIIIIIIIIIIIIIII</i>
	15. Elevation ((Show whether DF, RT, GR, etc.)		12. County
<u>VIIIIIIIIIIIII</u>				Eddy
Cł	heck Appropriate Box To	Indicate Nature of Notice, Rep	ort or Oth	er Data
NOTICE	OF INTENTION TO:	SUB	BSEQUENT	REPORT OF:
			·	_
PERFORM REMEDIAL WORK	PLUG AND	ABANDON XX REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	·	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE P	LANS CASING TEST AND CEMENT J	108	
		OTHER		L_
OTHER	· · · · · · · · · · · · · · · · · · ·	L_J		
17. Describe Proposed or Compl	leted Operations (Clearly state al	l pertinent details, and give pertinent date	es, including	estimated date of starting any proposed
work) SEE RULE 1103. Tests indicate that the casing is collapsed at approximately 2275'. Therefore we plan to plug				
and abandon this well in the following manner:				
Shoot and pull tubing from approximately 2275'. Set a cement retainer as low as possible and				
pump hole below retainer full of mud then squeeze with a 35 sack cement plug. Shoot off 5 1/2"				
casing at lowest free-point and pull. If casing parts above bottom of salt section at approx-				
imately 1500', perforate and squeeze 35 sack cement plug at bottom of salt section. If casing parts below bottom of salt section set 35 sack cement plug in and out of casing stub. Set 35				
sack cement plug in and out of surface pipe from approximately 560' to 460'. Shoot off surface				
casing and pull. Set 10 sack plug at surface with regulation marker. Fill hole between all				
plugs with mud.	20	. Surface with regulation	indi Ker .	Fill hole between all
The Commission will be notified when operations are commenced.				
The Commission will be notified when operations are commenced. She Hg @ 2340 - Connet pumpin W 2200 * to set BPC 2340 + Separations				
hat the 0 2300 - Connot prempter as services and				
571-7 0				
18 I hereby cartify that the lafa	mation shows is true and complet	te to the best of my knowledge and belief.		
		A source and service and beller.	•	
	4 Millo	MA access		0/1//74
SIGNED TIMES	4. M Jonard	TITLE Office Manager		DATE 8/16/74
, //				
1.5 /1	" Marsott	TITLE OIL AND GAS INSPECTOR		AUG 2 0 1974
APPROVED BY	por man.	TITLE <u>VIL ANU GAS INSPECTOA</u>		DATE
CONDITIONS OF APPROVAL, I	IF ANY:			
asm	steel above			