

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30015048020051
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	North Square Lake Premier Unit
8. Well No.	18
9. Pool name or Wildcat	Square Lake (G/SA) North
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Walsh & Watts Inc.
3. Address of Operator 1111 Seventh Street, Wichita Falls, TX 76301	4. Well Location Unit Letter W : 660 Feet From The South Line and 1980 Feet From The East Line Section 5 Township 16-5 Range 31-E NMPM Eddy County

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 4 1/2 C.I.B.P at 3350', Spot 14 sacks cement on top of C.I.B.P.
- Load hole with mud
- Perforate casing at 1900', unable to pump into perforations, talked to N.M.O.C.C. Ray Smith; he ok'd to spot cement aeruss perforations at 1900', spot 25 sacks cement at 1950'
- Perforate casing at 1300', squeeze 50 sacks cement at 1500 psi, shut in pressure W.O.C, tag cement top at 1210'
- Perforate casing at 285' circulate cement to surface between 4 1/2 & 5" with 100 sacks Set P A marker
- Job completed 8/16/95

Post ID-2  
9-15-95  
P&A

RECEIVED

SEP 6 1995

OIL CON. DIV.

DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim Heaton TITLE Manager, Pride P & A Div. DATE 8/22/95

TYPE OR PRINT NAME Jim Heaton TELEPHONE NO. 683-5321

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 9/29/95

CONDITIONS OF APPROVAL, IF ANY: