= :	ICES AND REPORTS		LC-056302A  6. IF INDIAN, ADDOTTER OF	R TRIBE N
(Do not use this form for propos Use "APPLICA	als to drill or to deepen or plug TION FOR PERMIT—" for such i	back to a different reservoir. proposals.)	N/A	
GIL 🟋 GAS	K	7. UNIT AGREEMENT NAME		
WELL WELL OTHER		<del>x 9 5 1993</del>	N/A	
SDX RESOURCES, INC.	JA	M to 1000	8. FARM OR LEASE NAME Kennedy Johnson	on A
. ADDRESS OF OPERATOR		9. WBLL NO.		
P. O. Box 5061	Midland, TX 79	79704-5061		
See also space 17 below.)	early and in accordance with any	State requirements.*	10. FIELD AND POOL, OR W	
At surface			Grayburg Jacks	
Unit F Sec. 35 T16S R31E	LCC16 -	1 100.	11. SBC., T., R., M., OR BLE. SURVEY OR AREA	TMD
KJLE	1980 FN1. 8	1980 FNI & 1980 FWL		
4. PERMIT NO.	15. ELEVATIONS (Show whether Di	P, RT, GR, etc.)	12. COUNTY OR PARISE 13	3. STATE
			Eddy	NM
Check Ap	propriate Box To Indicate N	Nature of Notice, Report, o	r Other Data	
NOTICE OF INTENT			BEQUENT REPORT OF:	
TEST WATER SHUT-OFF	CLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	CULTIPLE COMPLETE	PRACTURE TREATMENT	ALTBRING CASIN	- [
	BANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*	
ـــــــ	HANGE PLANS	(Other)		
				EF . 11
Other)  DESCRIBE PROPOSED OR COMPLETED OPER proposed work. If well is direction nent to this work.)  Plan to re-activate we state/federal requires	ell, test casing for	completion or Reco	ctical depths for all markers and	starting d sones p
7 DESCRIBE PROPOSED OR COMPLETED OPER proposed work. If well is direction nent to this work.) •  Plan to re-activate we	ell, test casing for	Completion or Reco	tes, including estimated date of tical depths for all markers and	starting d sones p

## \*See Instructions on Reverse Side

## KENNEDY JOHNSON A-#1 F, Sec. 35, T16S, R31E Eddy County, New Mexico LC 056302A

Casing: 12 1/2" set at 56'.

7", 22#, set at 3461'.

Cemented with 528 sx with a 2 stage collar at 912'.

2nd stage 912'-surface. O.H. - 3461'-3871'.

## Plugging Procedure

- 1. Move in, rig up, nipple up BOP and dig workover pit.
- 2. Pull rods and pump. (Calculate depth by rod count.)
- 3. Circulate hole with salt gel.
- 4. Spot 35 sx plug 3561'-3361'.
- 5. Spot 25 sx plug 3000'-2850'.
- 6. Spot 25 sx plug 2000'-1850'.
- 7. Spot 25 sx plug 962'-812'.
- 8. Spot 10 sx surface plug and install dry hole marker.
- 9. Haul salvage to yard and clean location.

-+		+		LSE	E NAME <u>Ken</u> i	<u>ledy Jo</u>	n "A" #1FILE # hnson A Fed. L 1980 fnl	056302	
					[# ELD <u>GR-Jac</u> ]			S	
<del>-</del> ÷	+-	·		011	L PUR.	(30ii Q	GAS		
-	+ +-			DR:	ILL AND CO	MPLETE			
	: :		-	OR:	IG. OP. Fu	llerton	Oil Company	L.A., Calif.	
		<del></del>		SPI	UD DATE 7-1	8-38	KB Fin. Drlg.	8-20-38	
				Co	red from 3	629-387		<del></del>	
				TO	PS:				
CASIN	G ]	HOLE SIZE		WT. GRADE		sks	TOC	-+	
	]		12 1/2		45 or 56			<b>-</b> + <u> </u>	
	-	8 3/4	7	22	3461	528 to	sfs. Baker Gu 2 stage colla	ide shoe on	
COMPI	ETION		-	_					
3860- w/oil press	3871 to c	blank clean c	shell. To	otal no. would no	of Qts. in ot flow sho	<u>oaded a</u> n shots	-3695 80 Ots. inc. 3840-3860 and anchors 3 iorn. of Aug. 3	80 Ots.	
PERFS				<del></del>					
BOPD		I	BWPD	MCF:	PD	Вн	IP		
REME	IAL V	ORK A	ND WORKOVE	R					
DATE			WORK						
								<del></del>	
								······································	
D3.000									
DATE			_ WORK						
WELL	L INVENTORY: July 1985 Well has fill in it.  TUBING 2 7/8" set @ 3626.28  RODS 1 3/4"x2' sub, 75 3/4" jts., 63 jts. 7/8" 1 7/8"x2',1								
	7/8":	x8'sub	s	-					
	PACKER								
							ID#		
REMAI									