254

CHAINDY FIVE				-056302A	. ==	
	S AND REPORTS			MOINE, ALLOUITE	E OR TRIBE NAME	
(Do not use this form for proposals Use "APPLICATION")	to drill or to deepen or plug N FOR PERMIT " for such	back to a different reservoir.	N/	A		
915. TT GAS		n E 1000	7. UNI	T AGREEMENT N	AME	
WELL OTHER	4ر	N 2 5 1993	N/			
2 NAME OF OPERATOR		A C.D.	S. FAE	M OR LEASE NAI	Kr	
SDX RESOURCES, INC.		THE COURT F	Ke	nnedy Joh	nson	
	Midland, TX 7970	04-5061		L RO.		
4. LOCATION OF WELL (Report location clear)		State requirements.*	10. 71	LD AND POOL, O	R WILDCAT	
See also space 17 below.) At surface			1	ayburg Ja		
Unit F Sec. 35 T16S			11. sm	C., T., R., M., OR !	LE. AND	
R31E			•	SURVEY OR AREA	•	
	1980 FSL E	1980 FEL	Se	c. 35 T1	6S R31E	
14. PERMIT NO.	5. ELEVATIONS (Show whether DI	r, RT, GR, etc.)	12. cot	NTY OR PARISH	13. STATE	
			Ed	dy	NM	
16. Check Appro	priate Box To Indicate N	Nature of Notice, Report	, or Other Do	ata		
NOTICE OF INTENTION				QUENT REPORT OF:		
TEST WATER SHUT-OFF PCLL	OR ALTER CASING	WATER SHUT-OFF		REPAIRING V	VELI.	
FRACTURE TREAT MULT	IPLE COMPLETE	PRACTURE TREATMENT		ALTERING C		
SHOOT OR ACIDIZE ABAN	DON*	SHOOTING OR ACIDIZIN	IG	ABANDONME	(T*	
REPAIR WELL X CHAN	GE PLANS	(Other)				
	i——I	(Other)				
(Other) 17. UESCRIBE PROPOSED OR COMPLETED OPERATION proposed work. If well is directionally nent to this work.)*	ONE (Clearly state all pertinen drilled, give subsurface loca	(NOTE: Report : Completion or R	ecompletion Rep	ort and Log for	m.)	
(Other) 17. UESCRIBE PROPOSED OR COMPLETED OPERATION proposed work. If well is directionally	l, test casing for	(Note: Report Completion or R to details, and give pertinent tions and measured and true or T', A or plug ar April 30, 1993.	dates, including vertical depths	port and Log for g estimated dat for all markers accordin	m.) e of starting any s and sones perti	

*See Instructions on Reverse Side

TITLE _

SIGNED

(This space for Federal State office u

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

Vice-President

KENNEDY JOHNSON A-#2 J, Sec. 35, T16S, R31E Eddy County, New Mexico LC 056302A

Casing: 12 1/2" set at 56'.

7", 22#, set at 3559'.

Cemented with a 2 stage collar at 900'. Stage 1 - 393 sx.; stage 2 - 135 sx. (Calculate top 450')

O.H. - 3559'-3907'.

Plugging Procedure

- 1. Move in, rig up, nipple up BOP and dig workover pit.
- 2. Pull rods and pump. (Calculate depth by rod count.)
- 3. Circulate hole with salt gel.
- 4. Spot 35 sx plug 3659'-3459'.
- 5. Spot 25 sx plug 3000'-2850'.
- 6. Spot 25 sx plug 2000'-1850'.
- 7. Spot 25 sx plug 950'-800'.
- 8. Spot 10 sx surface plug and install dry hole marker.
- 9. Haul salvage to yard and clean location.

WELL DATA SHEET

-+	+	+		LOC AP: FII	E NAME <u>Ken</u> C. <u>J 35-1</u> I# ELD <u>GR</u> -Jac	nedy Joh 6s-31e kson O-G	nson A Fed.	E # <u>001000-02</u> LC <u>056302</u> <u>1980 fel</u> TUS <u>T</u>	
				DR:	ILL AND CO	MPLETE			
	: :	_		OR	IG. OP. Fu	llerton	Oil Company	<i>I</i>	
				SPI	UD DATE 9-	5-38	Pipe Set	9-30-38	
							PBTD		
	-	·		TO	PS:				
CASII	NG	HOLE SIZE		GRADE	SET	SKS	TOC	+	
	-		12 1/2 7		56	+ !	+ L	· i	
	-		at 900' 1s	22 st stage	3559 393 sxs -	528 Hal 2nd sta	liburton 2 ge 135 sxs.	stage collar Baker Float	
СОНРІ	LETIO:	1	Shoe on bo	ottom.				TOUT	
PERFS	<u> 10-1</u>	11-38	3660-3760,	3840-90	with 200 (Qts. Nit	ro. Cleane	d out to 3897.	
								<u> </u>	
Poter	ntiale	d 10-2	26-38 123	bo / 20	hre 5 25/) maf	thru 1" c		
2 "	BC	OPD	BWF	PD	MCFPD	INCI	thru 1" c	hoke on	
10-26-61 Well was cleaned out.									
			BWPD						
			ID WORKOVER		- D	ВНР	-		
			WORK						
DATE water	<u>8-10</u>	0-63 2 000# sa	1/2" E <u>UE I</u> and, 300# I	ynes Inf 2-15 Gyp	latable Pa	acker -	Frac w/1000	Ogals. slick	
			000gals. Re		_	10000#	gand		
						20000#	Janu.		
WELL	TUBIN	TORY: IG <u>11-1</u>	9-76 Ran 3	568' of	2 3/8"				
	RODS								
	PUMP								
	ANCHO								
	PACKE	R							
	MOTOR				TE)#	+ D II		
REMAR	KS: _				- PHZ I	~··			