orm 3160-5 November 1983) Formerly 9-331)		UNI.LD ST TMENT OF T AU OF LAND	THE INTER		00 20	Form approved. Budget Bureau No Expires August 31 5. LEASE DESIGNATION AN	. 1985 (
CLIN					-	LC-067849 6. IF INDIAN, ALLOTTER OF	
(Do not use this	form for proj Une "APPLI	TICES AND pomais to drill or to CATION FOR PER	KEPORIS (o deepen or plug l MIT—" for such p	ON WELLS pack to a different reservoir roposals.)		A COURT ADDITES U	A TRIDE NAME
DIL GAS WELL WELL	XX OTHER			RECEIVED		7. UNIT AGEBEMENT NAME	
Amoco Product	ion Comp	any 🗸				8. FARM OR LEAGE NAME Hondo Fed Gas	Com
P. O. Box 309		ton, TX 77	253	NCV 30 90		9. WBLL NO.	
LOCATION OF WELL (R	leport location	clearly and in acc	ordance with any	State requirements.		10. FIELD AND POOL, OR W	
At surface				ARTESIA, OFFIC		East Logan Draw	
Unit J, 1650	FSL and	2310 FEL		AKILING		11. SHC., T., R., M., OR BLK. SURVEY OR AREA	•
4. XENDROCK KOX API	#		(8)			27-17S-27E	
3001520937			(Show whether pr. 92' RDB	лт, GR, etc.)		12. COUNTY OR PARISE 15	
6.						Eddy	NM
	Check A	Appropriate Bo.(to Indicate N	ature of Notice, Repor		ner Data IT REFORT OF:	
TEST WATER SHUT-OF	·•	PULL OR ALTER (A	SING	WATER SHUT-OFF			[]
FRACTURE TREAT		MULTIPLE COMPLE	TE	FRACTURE TREATMEN	,	ALTERING CASIN	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZI	NG	ABANDON MENT*	
REPAIR WELL		CHANGE PLANS		(Other) Abandon	Morro	ω	X
(Other)			11	(Other) Abanton			
6/6/90: Move load	in and : casing.	rig up servi Release ra	ice unit. acker.	(Nors: Report Completion or) details, and give pertinen uns and measured and true Pump 40 bb1. dow	results of Recompletion t dates, ind vertical d	multiple completion on 1 on Report and Log form.) cluding estimated date of lepths for all markers and ng and 15 bbls	well starting any d zones perti-
7. DESCRIBE PROPOSED OR proposed work. If nent to this work.)* 6/6/90: Move load 6/7/90: Fini: log 6/8/90: Run cemen	in and s casing. sh layin from 8400 5-1/2" ca nt. Pers	rig up servi Release ra g down 2-3/8 D' to 5700'. ast iron bri E 6830 - 31'	ice unit. acker. 8" tubing a idge plug a ' with 4 sh	(Nors: Report Completion or) details, and give pertinen ions and measured and true Pump 40 bbl. dow nd packer and va nd set at 9250'	n tubi: n guns	multiple completion on 1 on Report and Log form.) cluding estimated date of lepths for all markers and ng and 15 bbls . Run pipe reco p with 35 ft. of	etarting any etarting any d sones perti- to overy f
 7. DESCRIBE PROPOSED OR proposed work. If nent to this work.) 6/6/90: Move load 6/7/90: Fini: log 6/8/90: Run cement 	in and s casing. sh layin from 8400 5-1/2" ca nt. Pers	rig up servi Release ra g down 2-3/8 D' to 5700'. ast iron bri E 6830 - 31'	ice unit. acker. 8" tubing a idge plug a ' with 4 sh	(Nors: Report Completion or) details, and give pertinen outs and measured and true Pump 40 bbl. dow nd packer and va nd set at 9250'	n tubi: n guns	multiple completion on 1 on Report and Log form.) cluding estimated date of lepths for all markers and ng and 15 bbls . Run pipe reco p with 35 ft. of	etarting any etarting any d sones perti- to overy f
 7. DESCRIBE PROPOSED OR proposed work. If nent to this work.) 6/6/90: Move load 6/7/90: Fini: log 6/8/90: Run cement 	in and s casing. sh layin from 8400 5-1/2" ca nt. Pers	rig up servi Release ra g down 2-3/8 D' to 5700'. ast iron bri E 6830 - 31'	ice unit. acker. 8" tubing a idge plug a ' with 4 sh	(Nors: Report Completion or) details, and give pertinen ions and measured and true Pump 40 bbl. dow nd packer and va nd set at 9250'	n tubi: n guns	multiple completion on 1 on Report and Log form.) cluding estimated date of lepths for all markers and ng and 15 bbls . Run pipe reco p with 35 ft. of	to to to to to to to to to to
 7. DESCRIBE PROPOSED OR proposed work. If nent to this work.) 6/6/90: Move load 6/7/90: Fini: log 6/8/90: Run cement 	in and s casing. sh layin from 8400 5-1/2" ca nt. Pers	rig up servi Release ra g down 2-3/8 D' to 5700'. ast iron bri E 6830 - 31'	ice unit. acker. 8" tubing a idge plug a ' with 4 sh t 6782'. P	(Nors: Report Completion or) details, and give pertinen ions and measured and true Pump 40 bbl. dow nd packer and va nd set at 9250'	n tubi: n guns	multiple completion on 1 on Report and Log form.) cluding estimated date of lepths for all markers and ng and 15 bbls . Run pipe reco p with 35 ft. of arrow set and n 5-1/2" casing	etarting any etarting any d sones perti- to overy f
 7. DESCRIBE PROPOSED OR proposed work. If nent to this work.)* 6/6/90: Move load 6/7/90: Finition 6/8/90: Runtion 6/8/90: Runtion cementiation 	in and s casing. sh laying from 8400 5-1/2" ca nt. Per: ng and pa	rig up servi Release ra g down 2-3/8 D' to 5700'. ast iron bri E 6830 - 31' acker set at	ice unit. acker. 8" tubing a idge plug a ' with 4 sh t 6782'. P	(Nors: Report Completion or) details, and give pertinen outs and measured and true Pump 40 bbl. dow nd packer and va nd set at 9250' ots; run Watson ump 20 bbls. wat	results of <u>Recompleti</u> t dates, ind r tubi: n guns and ca 5-1/2" er down	multiple completion on 1 on Report and Log form.) cluding estimated date of lepths for all markers and ng and 15 bbls . Run pipe reco p with 35 ft. of arrow set and n 5-1/2" casing	to overy f
 7. DESCRIBE PROPOSED OR proposed work. If nent to this work.)* 6/6/90: Move load 6/7/90: Finit log 6/8/90: Run cement tubin 	in and casing. sh laying from 8400 5-1/2" ca nt. Per: ng and pa ng and pa	rig up servi Release ra g down 2-3/8 O' to 5700'. ast iron bri f 6830 - 31' acker set at	ice unit. acker. 8" tubing a idge plug a ' with 4 sh t 6782'. P	(Nors: Report Completion or) details, and give pertinen ons and measured and true Pump 40 bb1. dow nd packer and va nd set at 9250' ots; run Watson ump 20 bb1s. wat	results of <u>Recompleti</u> t dates, ind r tubi: n guns and ca 5-1/2" er down	multiple completion on 1 on Report and Log form.) cluding estimated date of lepths for all markers and ng and 15 bbls . Run pipe reco p with 35 ft. of arrow set and n 5-1/2" casing	to very f
 7. DESCRIBE PROPOSED OR proposed work. If nent to this work.)* 6/6/90: Move load 6/7/90: Finition 6/8/90: Runtion 6/8/90: Runtion cementiation 	in and casing. sh laying from 8400 5-1/2" ca nt. Per: ng and pa ng and pa	rig up servi Release ra g down 2-3/8 O' to 5700'. ast iron bri f 6830 - 31' acker set at	ice unit. acker. 8" tubing a idge plug a ' with 4 sh t 6782'. P	(Nors: Report Completion or) details, and give pertinen outs and measured and true Pump 40 bbl. dow nd packer and va nd set at 9250' ots; run Watson ump 20 bbls. wat	results of <u>Recompleti</u> t dates, ind r tubi: n guns and ca 5-1/2" er down	multiple completion on 1 on Report and Log form.) cluding estimated date of iepths for all markers and ng and 15 bbls . Run pipe reco p with 35 ft. of arrow set and n 5-1/2" casing	to very f
 7. DESCRIBE PROPOSED OR proposed work. If nent to this work.)* 6/6/90: Move load 6/7/90: Finit log 6/8/90: Run cement tubin 	in and casing. sh laying from 8400 5-1/2" ca nt. Per: ng and pa ng and pa	rig up servi Release ra g down 2-3/8 D' to 5700'. ast iron bri 6 6830 - 31' acker set at	ice unit. acker. 8" tubing a idge plug a ' with 4 sh t 6782'. P	(Nors: Report Completion or) details, and give pertinen outs and measured and true Pump 40 bbl. dow nd packer and va nd set at 9250' ots; run Watson ump 20 bbls. wat	results of <u>Recompleti</u> t dates, ind r tubi: n guns and ca 5-1/2" er down	multiple completion on 1 on Report and Log form.) cluding estimated date of iepths for all markers and ng and 15 bbls . Run pipe reco p with 35 ft. of arrow set and n 5-1/2" casing	to very f

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, firstitious or fraudulant etaportectory of the sector is a sector is a sector of the sector is a sector of the sector is a sector of the secto