

June 24, 1974

AMOCO Production Company

Hobbs, New Mexico

Attn: Drilling Dept.

RE: BOP Test - Your Pavo Mesa #1

Gentlemen:

We made a hydrostatic pressure test to captioned blowout control equipment on June 21, 1974, and wish to advise the following:

At the conclusion of testing:

- Valves: 1. Leak thru drill pipe safety valve -
to be repaired or replaced as needed.
2. Leak thru wing valve off manifold
cross (pit side) - to be repaired or
replaced as needed.

Separate tests were made at the pressure of 3000# to blind rams, pipe rams, upper kelly cock, and to the valves and fittings of the bop stack proper. No further testing desired to the chokeline or choke-manifold.

There were no visible leak to items tested at the conclusion of testing other than as mentioned above.

A delay was observed to operation of blowout control equipment at the conclusion of testing - unable to retain closing pressure on rams (corrected as needed). Closures were made using closing unit pump only to the observed pressure of 2500# for test to ram type bops. Accumulators depleted at end of test. Control valves operated as indicated on closing unit manifold at end of test. Bop extentions were not hooked up.