

b. If well does not go on vacuum after perforating, spot acid across perfs. Set packer @ 6000 and acidize well with 1500 gallons 15% HCL. Maximum pressure 1000 psi.

7. Swab Test well and evaluate same.

a. If non productive continue @ step # 8

b. If productive Run Ca as per production and TOTPS.

8. Kill well and POOH. Set CIBP @ 6050' and cap w/ 35' cement. TIH and circulate with TBW. LD tubing string. ND BOPE and TA well.

M. W. Gore

for 1/8/91
Concur: R. D. Reynolds

J. E. Shields