Submit 3 Copies to Appropriate Distort Office

## State of New Mexico ergy, Minerals and Natural Resources Departs.

Form C	
Revised	1.1-09 (

DISTRICT I P.O. Box 1980, Hobbe, NIM 88240

## OIL CONSERVATION DIVISION WELL AFIND

LL API NO.

P.O. Box 1980, Hobbs, NM 88240	P.O. Box		30-015-22226
Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210		S. Indicate Time of Lease	
DISTRICT III 1000 Rio Brazos Rd., Azzoc, NM 87410			STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410			# 200 OR & ORS PERSON LIGO
SUNDRY NOTICES	AND REPORTS ON W	/ELLS	
( DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIS	ALS TO DRILL OR TO DEEP 2. USE "APPLICATION FOR	TEN OR PLUG BACK TO A PERMIT	7. Lease Name or Unit Agreement Name
(FORM C-101)	FOR SUCH PROPOSALS.)		EMPIRE ABO UNIT "F"
L. Type of Well: Oil GAS WELL X WELL	ones.	RECEIVED	MATRIC ADO GATE
2 Name of Operator ARCO OIL & GAS COMPAN	v /	MAD 0 0 1401	8. Well No. 333
1. Address of Operator	1 0	MAK 2 9 1991	9. Pool same or Wildcat
BOX 1710, HOBBS, NEW	MEXICO 88240	U. L. D.	EMPIRE - ABO
4. Well Location E 1286	WEST	160	2 NORTH
Unit Letter : 1286	Feet Prom The	Line and	Feet From The NONTH Line
Section 34	Township 17S	Range 28E	NMPM Eolol County
	10. Elevation (Show whether	her DF, RKB, RT, GR, etc.)	
	3672.7 GR		Sill Sill Sill Sill Sill Sill Sill Sill
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTEN	TION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
	_	CASING TEST AND CE	MENT, IOR
PULL OR ALTER CASING	_	n	- <u> </u>
OTHER:		J OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
TA & HOLD WELL BORE FOR FIELD BLOW DOWN			
1. Notify NMOCD 24 hrs. prior to testing CIBP			
2. MIRU			
<ul><li>3. Unset PKR or TAC</li><li>4. Install BOP &amp; GIH to tag PBTD</li></ul>			
5. POH w/TBG, TOH			
6. GIH w/TBG or WL set CIBP			
7. Set CIBP maximum 50' above existing PERFS			
8. POH w/l Jt. & circ a mix of 2 gal WT675 chem. per 10 bbls 8.6# brine			
9. When circulation is established, w/ treated fluid at surface, test CIBP to 500#			
and cut chart.  10. POH, laying down -	leave l Jt. hangi	ng on BI Bonnett	
I hereby cartify that the information above is true and or	complete to the best of my knowledge	and belia. Administrative	Supervisor March 11, 1991
SIGNATURE Janey Color		TITLE	DATE
TYPE OR PROFT HAVE			TELETHONE NO.
(This space for State Use)		(1-11) D	11/- 1-

Test CIBP