

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
**30-015-22487**

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
**E-7842**

7. Lease Name or Unit Agreement Name  
**Empire Abo Unit "E"**

8. Well No.  
**361**

9. Pool name or Wildcat  
**Empire Abo**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITTED (FORM C-101) FOR SUCH PROPOSALS.")

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
**ARCO Permian**

3. Address of Operator  
**P.O. Box 1089 Eunice, NM 88231**

4. Well Location  
Unit Letter **A**; **620** Feet From The **N** Line and **1200** Feet From The **E** Line  
Section **34** Township **17S** Range **28E** NMPM **Eddy** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
**3671.6' GR**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6294' PBD: 6274' PERFS: 6020-6030' 4" liner @ 6058-6274'

09/08/99: NUBOP. TIH w/ RBP, retrieving tool on 2-3/8" tbg to 2800'. TOH. RIH w/bailer. Run 2-3/8" tbg to 6010'. Tag CIBP @ 6010'.

09/09/99: Notified NMOCD. Gary Williams present. Pmp 25 sxs cmt plug 5920-5820'. Pull above plug to 5700'. Displace 5-1/2" csg volume w/32 Visc SW Gel. Spot Plug #2 @ 3475-3375' w/ 25 sxs "C" Neat cmt w/3% Calc Chloride. SI 3 hrs, WOC. RIH to 3485'. Did not tag #2 plug. Pull up to 3475'. Spot #3 plug w/50 sxs cmt.

09/10/99: Lower tbg to TOC @ 3330'. OK. Set cmt plug #4 @ 2193-2080'. TOH. Set cmt plug #5 @ 1100-1200'. TOH. Set cmt plug #6 @ 800-700'. SI 3 hrs. Tag TOC plug #6 @ 672'. NDBOP. Fill 5-1/2" csg 30' to surf. Well P&A'd 09/10/99.

*Post ID-2  
10-1-99  
P&A*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Kellie D. Murrish* TITLE Administrative Assistant DATE 09/22/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: