

RECEIVED

WORKOVER PROCEDURE

DATE: 7/1/90

OCT 19 '90

WELL & JOB: EAU F-352

RECOMPLETE

DRILLED: 1978

O. C. D.
ARTESIA, OFFICE
COUNTY: Eddy, NM

LAST WORKOVER: 1898
1986

FIELD: Empire Abo

BY: GORE

TD: 6283' ,

PBD: 6130' CIBP

DATUM: RKB 12'

TUBINGHEAD:

SIZE:

PRESS RATING:

CASING:	SIZE	WEIGHT	GRADE	SET @	SX CMT	TOC
SURFACE:	8-5/8"	24#	J-55	753'	600	SURFACE
INTER:						
PROD:	5-1/2'	15.5	K-55	6283'		Surface

PERFORATIONS: Abo 6202'-22'; 6140'-50' ; 6096'-104'

TUBING:	SIZE:	WEIGHT:	GRADE:	THREAD:
BTM'D @	2-3/8'	4.7#	J-55	EUE
	JOINTS: 194	MISC:		

PACKER AND MISC: Baker Lok-Set

SCOPE OF WORK: Recomplete to upper Abo.

PROCEDURE

1. MIRU PU. Kill well. NU BOPE.
2. POOH w/ CA.
3. Set CIBP @ 6075' on wireline. Load and test casing to 500 psi.
4. Perforate Abo 6054' - 6064' w/ 2 JSPF. If well goes on vacuum after perforating TIH w/ packer and set same @ 5950'. Swab Test same. If well does not go on vacuum spot 100 gallons across perfs. Set packer @ 5950' and acidize w/ 1500 gallons 15% NEFE. Limit treating pressure to 1000 psi.
5. Swab test for evaluation.
6. If productive kill well and run CA as per production. If non productive kill well and POOH w/ packer. Set CIBP on wireline @ 6030'. Load and test casing to 500 psi.
7. Perforate Abo 6008' - 6016' w/ 2 JSPF. Observe same procedure as above.
 - a. If on vacuum swab test.
 - b. If not on vacuum. TIH and spot acid and acidize w/ 1500 gallons 15% NEFE.
8. Swab test to evaluate.
 - a. If productive kill well and run CA as per production supervisor.