420 4302

MURCHISON OIL AND GAS, INC. Berry Federal Com #1 Seo.28, T-17S, R-27E 1980' FNL and 660' FWL Eddy County, New Mexico

PROPOSED P&A PROCEDURE

September 20, 2000

CASING:

Surface	13 3/8" - 14.1	5# J-55	@ 282'	Cmt Cir.
Intermediate	8 5/8" - 2 4#	K-55	a 1,721'	Cmt Cir.
Deep Intermediate	4 1/2" - 11.6	i#, 10.5# K-55	N <i>Y</i>	Cmt w/ 1375 sxs
				TOC 5400' by CBL

KB 15'

TUBING DETAIL:

2 3/8" J-55 eue 8rd tbg, with 4 1/2" Lok-Set packer set at 7,745'. Tbg will be used to set cement plugs.

EQUIPMENT:

One 300 Bbl steel oil tank and 500 BTU gas production will be checked for salvage value or junked.

PROCEDURE:

- 1. Prepare location, test dead men, out out flow line, and set rig matting board.
- 2. Move in and rig up pulling unit.
- 3. Blow down tbg and csg, and load with fresh water.
- 4. ND tree and NU 3K 6" 1500 x 2 3/8" BOP. NOTE: (Well head bolts made need to be out off) Set frac tank for circulation tank.
- 5. Release packer and circulate hole with 10# salt gel, POOH w/ tbg and packer.
- 6. RU wireline and run gauge ring and junk basket to CIBP at 8000'. TIH w/ dump bailor and dump bail 30' of omt on CIBP at 8000'. TIH w/ CIBP and set above Wolfcamp at 6100' and dump bail 30' of omt on plug at 6100'.
- 7. NDBOP dig out cellar bleed off surface and load with water and ND tbg head. NU 10" x 41/2" BOP.

Murchison Oil and Gas, Inc. Berry Federal Com #1