STATE OF NEW MEXICO			
ENERGY AND MINERALS DEPARTMENT	OIL CONSERVATION DIVISION		
DISTRIBUTION	P. O. BOX 2088	Form C-103	
SANTAFE B	р. 0. вох 2088 Santa Fe, new mexico 87501 FEB 01 '88	Revised 10-1-78	
PILE NV	FEB 01 '88	Sa. Indicate Type of Lease	
<b>U.S.G.S.</b>		State X Fee	
LAND OFFICE	O C. D.	5, State Oll & Gas Lease No.	
OPERATOR I	RTESIA, OFFIC		
SUNDRY NOTIC	ES AND REPORTS ON WELLS		
		7. Unil Agreement Name	
2. Name of Operator		8. Form or Lease Hame	
ARCO Oil and Gas Company		Empire Abo Unit "È"	
13. Address of Operator		9. Well No.	
P.O. Box 1610, Midland, Te	exas 79702	363	
4. Legation of Well	<u> </u>	10. Field and Pool, or Wildcat	
A 650	North 120	Empire Abo	
East 34	TOWNBHIP LINE AND 28E		
	15. Elevation (Show whether DF, RT, GR, etc.) 3673.5 GR	12. County Eddy	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: I SUBSEQUENT REPORT OF:			
	PLUE AND ABANDON	ABTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		
erate <u>Recomplete sa</u>	me zone X		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

Propose to set CIBP, come up hole and recomplete same zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

.

.

	Engr. Tech. 915-688-5672	DATE 1-27-88
Original Signed By Mike Williams CONDITIONS OF APPROVAL, IF ANY:	117L8	FEB 4 1988

.

.

## RECEIVED

FE3 01 '88

## WORKOVER\_PROCEDURE

DATE\_9/25/87\_\_\_\_O.C.D. ARTESIA, OFFICE WELL NO. & TYPE OF JOB: <u>Empire Abo Unit #E-363</u> ARCO WI: 34.1406% JOB TITLE: <u>Test Existing Perfs/Plug Back and Reperforate</u> DRILLED & COMPLETED: \_\_11/79\_\_\_\_ LAST WO: \_\_\_12/86\_\_\_\_ FIELD: <u>Empire Abo</u> \_\_\_\_ COUNTY: <u>Eddy County, NM</u> PREPARED BY: <u>M.B. Smith</u> TD: 6350' PBD: 6178' DATUM: RKB DIST RKB TO GL: 10.5' MAKE\_\_\_NA\_\_\_\_\_ SIZE\_\_\_7-1/16\_\_ PRESSURE RATING\_\_3000\_Psi\_\_\_\_ TUBINGHEAD: CASING INFORMATION: SIZE WEIGHT <u>SET</u> GRADE SX CMT TOC <u>800'</u> <u>450</u> <u>Surface</u> DV e 3025' 1050 Surface \_8-5/8" \_24\_ \_K-55\_ SURFACE: PRODUCTION: 5-1/2" 15.5 <u>\_K-55</u> <u>6350'</u> <u>\_600</u> <u>\_3025'(CBL)</u> PRESENT PERFORATIONS\_<u>Bmpire\_Abo\_6150-6156\_(14\_Holes)</u> TUBING SIZE: 2-3/8" WT: 4.7# GRD: J-55 THD: EUE\_8R NO JTS: 195 @ 6118'\_\_ PACKER & MISC.: <u>Baker Lok-set packer set at 6118</u>' with 6000 lbs tension. \_\_\_\_\_Fluid-Pac\_cavity\_above\_packer.\_\_SI\_since\_4/1/87.\_\_Last\_production\_test\_\_\_\_ \_\_\_\_\_3/8/87 was 8 BOPD, 245 BWPD and 26 MCFGPD.

## PROCEDURE

- Test anchors. MIRU PU. Check well for pressure and bleed off. Kill well w/produced water as necessary. ND wellhead and NU BOP.
- 2. Swab test the current Empire Abo perforations and report influx of fluid to Midland.
- 3. Assuming the original perforations are noncommercial, POH with tubing and packer (visually inspect the tubing, Hydro-test to 3500 psi above the slips if the tubing condition is questionable). WL set a 5-1/2" CIBP at 6130'. Load the hole with produced water and pressure test to 500 psi.
- 4. Perforate the Empire Abo from 6090' to 6096' with 2 JSPF (14 holes). Correlate to Dresser Atlas Density/Neutron log dated 2/11/79. Note fluctuation in fluid level after perforating. If well goes on a vacuum proceed with swab testing prior to performing the acid job.
- 5. TIH with treating packer and 2-3/8" SN on 2-3/8" tubing. to 6096'. Spot 100 gal acid across perforations and pull packer up hole to  $\pm 6040$ '. Reverse 5 bbls water up tubing and set packer.
- Pressure annulus to 500 psi and acidize the Empire Abo perforations with 800 gal 70/30 15% NEFE HCL acid and xylene at 1-3 BPM. Flush to the bottom perforation with produced water. Maximum treating pressure 1000 psi.

Page 2 Empire Abo Unit #E-363 Workover Procedure

7. SWI for 30 minutes and swab test.

If the well is productive continue with step 10.

If the well is not productive continue with step 8.

8. WL set a CIBP at 6080' and perforate the Empire Abo from 6052 - 6060 w/2 JSPF. Spot acid and Acidize as necessary with 800 gal of 15% NEFE HCL acid at 1-3 BPM with a 1000 psi maximum wellhead treating pressure. SI for 30 minutes and swab test.

If the well is productive continue with step 10.

If the well is not productive continue with step 9.

- 9. WL set a CIBP at 6042' and perforate the Empire Abo from 6032 6038 w/2 JSPF. Spot acid and Acidize as necessary with 600 gal of 15% NEFE HCL acid at 1-3 BPM with a 1000 psi maximum wellhead treating pressure. SI for 30 minutes and swab test.
- 10. POH with tubing and packer. TIH with completion assembly as per production department specifications. TOTPS.



