

RECEIVED

9. Perf the 5-1/2" CSG w/ 2 JSPF using a 4" CSG gun f/ 6097 - 6112' (30 - .42" holes).

If well goes on vacuum, swab test. If well does not go on vacuum, proceed to step #10. JUL 30 '90

10. RIH w/ RET PKR on 2-3/8" Prod TBG to 6114'. Spot 100 gal 15% NEFE HCl acid across perfs 6097 - 6112'. PU, RVS 5 BBLs, and set PKR @ $\pm 5997'$. PA TO 500#. G-6 Perfs 6097
ARTESIA, OFFICE

11. Acidize Abo perfs 6097 - 6112' w/ 1000 gal 15% NEFE HCl acid @ 1 BPM. Flush to bottom perf w/ clean produced water. MAXP: 1000#.

12. SI for 30 minutes, recording surf press every 10 minutes.

13. Swab/flow back and evaluate. If zone is productive, proceed to step 21, otherwise go to next step.

14. POH w/ TBG and PKR. WL set CIBP @ 6080'. Test to 500#.

15. Perf the 5-1/2" CSG w/ 2 JSPF using a 4" CSG gun f/ 6042 - 6052' (20 - .42" holes).

If well goes on vacuum, swab test. If well does not go on vacuum, proceed to step #16.

16. RIH w/ RET PKR on 2-3/8" Prod TBG to 6054'. Spot 100 gal 15% NEFE HCl acid across perfs 6042 - 6052'. PU, RVS 5 BBLs, and set PKR @ $\pm 5942'$. PA TO 500#.

17. Acidize Abo perfs 6042 - 6052' w/ 1000 gal 15% NEFE HCl acid @ 1 BPM. Flush to bottom perf w/ clean produced water. MAXP: 1000#.

18. SI for 30 minutes, recording surf press every 10 minutes.

19. Swab/flow back and evaluate. If zone is productive, proceed to step 21, otherwise go to next step.

20. POH w/ TBG and PKR. WL set CIBP @ 5600' to TA well pending engineers evaluation.

21. POH w/ TBG and PKR. RIH w/ CA as per Production Department specifications. ND BOP. NU WH. RD PU. RR. Clean Location. TOPS.


D.C. BRETCHES