ENERGY AND MINERALS DEPARTMENT DISTRIBUTION SANTA FE U.S.O.S. MAY 1 1983	Form C-103 Revised 10-1- Sa. Indicate Type of Lesse State X 5 ce
DISTRIBUTION PO. BOX 2008 EVED SANTA FE SANTA FE NEW MEXICO 87501	Revised 10-1- Sa. Indicate Type of Lesse State X 5 or
SANTA FE SANTA FE NEW MEXICO 87501	Revised 10-1- Sa. Indicate Type of Lesse State X 5 or
SANTA FE SANTA FB NEW MEXICO 87501	Sa. Indicate Type of Lesse State X 5 ve
	State X 5 00
MAI 1 LISUS	
	5. State Off & Gas Lease No.
O. C. D.	B-2077
SUNDRY NOTICES AND REPORTS ON WARTESIA, OFFICE	
OIL GAS IN OTHER-	7. Unit Agreement Name
Name of Operator	8. Farm or Lease Hame
Amoco Production Company 🗸	State MO
Address of Operator	9. Well No.
P. O. Box 68, Hobbs, New Mexico 88240	1
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER F. 1320 FEET FROM THE NORth LINE AND 1320 FEET	Und. Atoka
THE West LINE, SECTION 27 TOWNSHIP 17-S RANGE 28-E	. кмрм. ДЛЛЛЛЛЛЛЛЛЛЛЛЛЛЛЛЛЛЛЛ
() [] [] [] [] [] [] [] [] [] [] [] [] []	12. County
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Eddy
Check Appropriate Box To Indicate Nature of Notice, Report of	
	JENT REPORT OF:
RFORM REMEDIAL WORK	ALTERING CASING
EMPORABILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
ULL OR ALTER CASING	_
Change zones	
OTHER_UTINING ZUTIES	
, Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any propose

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to abandon the Wolfcamp by squeezing the interval 7920'-7972' and complete in the Atoka interval 9890'-9902' and acidize as necessary per the following:

Move in and rig up service unit. Well is currently shut-in. Kill well with brine water. BHP is approx. 3200 psi based on swab tests. Release packer and pull tubing, packer, and tailpipe. RIH with cement retainer on end of 2-3/8" tubing. Set at 7820' and test retainer by stinging out and then back-in. Establish an injection rate. Squeeze the Wolfcamp intervals 7920'-7972' with 200 sx class H neat cement. Squeeze perfs to 1500 PSI surface treating pressure. After obtaining squeeze pressure of 1500 psi, sting out of retainer and reverse circulate cement out of tubing string. POH with tubing. Shut-in and WOC. RIH with drill bit on 2-3/8" tubing and drill out cement. Pressure test squeeze to 1000 psi. Run bit to 9950' and circulate hole with 2% KCL brine water. POH with bit. RIH with a3-1/8" hollow carrier casing gun and perforate the Atoka interval 9890'-9902' with 4 JSPF with 90° phasing. POH with casing gun and run in hole with tubing as follows: a) Run 3 jt of 2-3/8" tailpipe with a 8000 psi shear disc assembly on bottom and a 1.81" seating nipple one jt. off bottom.

APPROVED BY		Original Signed By Loslie A. Clements Supervisor District II	MAY 1 2 1983	÷
PIENER Charles M	n. Herring	une Assist. Admin. Analyst	DATE5-10-83	