

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 208
SANTA FE, NEW MEXICO 87501

RECEIVED BY
MAR 27 1987
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-79

5. Indicate Type of Lease
State ☐ Fee ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Haines ACG
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER K 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 17S RANGE 27E NMPM.	10. Field and Pool, or WHdcat Logan Draw SA
15. Elevation (Show whether DF, RT, GR, etc.) 3293' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows:

Spot 100 sx plug at 1838' (across perforations 1572-1838'). WOC.
RIH w/tubing to 1838' with no tag. Mix and spot 10 sx LCM across perforations.
Pulled up hole and waited 1 hour. RIH w/tubing to 1888'.
Spot 35 sx cement plug at 1888'. Tagged plug at 1683'.
Consulted with NMOCD, Artesia.
Mix and spot 5 sx LCM.
Spot 30 sx plug at 1683'. WOC. Tagged plug at 1400'.
Mixed mud and circulated hole.
Spot 25 sx cement plug at 400'.
Spot 10 sx cement surface plug.

Weld on cap and dry hole marker.
Plugging completed 3-24-87.

Post ID-2
4-3-87
PVA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Janita Doodlett</i></u>	TITLE <u>Production Supervisor</u>	DATE <u>3-25-87</u>
APPROVED BY <u><i>Danell Moore</i></u>	TITLE <u>Geologist</u>	DATE <u>9/12/88</u>
CONDITIONS OF APPROVAL, IF ANY:		