			c151-
Form 3 160-5 (June 1990)	DEPARTMEN	TED STATES NT OF THE INTERIOR LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 3 1 ,1993 5. Lease Designation and Serial No.
	form for proposals to dr	AND REPORTS ON WELLS ill or to deepen or reentry to a different reservoir. OR PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
	SUBMIT	IN TRIPLICA TE	7. If Unit or CA, Agreement Designation
1. Type of Well			
Well Well		8. Well Name and No.	
2. Name of Operator		State U-5 #3	
	Conoco Inc		9. API Well No.
3. Address and Telephone		X 70705 (500 (045) 000 5500	30-015-02908
10 DESTA DR. STE. 100W, MIDLAND, TX 79705-4500 (915) 686-5580			10. Field and Pool, or Exploratory Area
4. Location of Well (Foo	tage. Sec., T. R. M. or Survey De	scription)	Grayburg
	1980' FNL & 660'	11. County or Parish, State	
			Eddy, NM
In CHECK	APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	T, OR OTHER DATA
TYPE OF	SUBMISSION	TYPE OF ACTION	
Notice	of Intent	Abandonment	Change of Plans
[]		Recompletion	New Construction
Subseq	uent Report	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
Final A	bandonment Notice	Altering Casing	Conversion to Injection
		Other	Dispose Water Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

	Completion of Recompletion Report and Edg Johns,
13. Describe Proposed or Completed Operations (Clearly state al	I pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled,
give subsurface locations and measured and true verti	cal depths for all markers and zones pertinent to this work.)*

The subject well was originally plugged and abandoned in July, 1957. Upon a recent inspection, it was reported that oil was leaking at the surface. The well will be re-plugged per the attached procedure.



4. I hereby certify that the foregoing is true and correct	d correct Reesa R. Wilkes Image: Construction of the second sec	
Signed Nelsa Wilkes		Date 11/28/01
(This space for Federal or State office use)		
Approved by Conditions of approval if any:	Title	Date
BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FI	ELD, FILE ROOM	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Proposed re-entry/plug, ... g procedure Conoco Inc. - State U-5 #3 API #30-015-02908; 1980 FNL & 660 FWL, Unit Letter E, Section 5, T-17-S, R-29-E Eddy County, New Mexico

History:	Well was originally drilled in April of 1957 to 2,440' and completed in Grayburg with perforations 2,380 – 2,388'. In July of 1957, the well was plugged per attached wellbore diagram as a dry hole. NMOCD inspection October 31, 2001 indicates a possible oil leak at surface.
Surface casing:	7-5/8" 26.4# set @ 715' cemented w/ 360 sx, circulated to surface.
Production casing:	4½" 9.5# csg set @ 2,439' cemented w/ 75 sx, TOC 1,925' by T.S., cut and pulled +/- 1900' 4½" casing during P&A in 1957.
Existing Plugs:	2,437 – 2,337'; 1,550 – 1,450'; 765 – 665'; 25' to surface
Formation Tops:	Yates 840' Seven Rivers 1,074' Queen 1,632'

Notify New Mexico OCD, Van Barton, at 505-748-1283. Move in backhoe and dig out dry hole marker to casings to determine source of oil-soaked soil at surface around dryhole marker. If source of oil is not the wellbore, re-mediate contaminated soil without entering wellbore or removing dryhole marker. If wellbore appears to be leaking, re-enter wellbore as follows:

- 1. Dig out cellar to 7-5/8" surface casing. Remove dryhole marker. Implement confined space and excavation procedures if dug out more than three feet below ground level. Dig, line, and fence 200 bbl working pit.
- 2. Following hotwork safety procedures, verify safe hotwork environment and weld on 7-5/8" riser to ground level and weld on wellhead flange.
- 3. Set rig anchors and test per AESC guidelines.
- 4. Set steel rig mat and 2,500' 2-3/8" workstring. MIRU pulling unit and reverse unit. NU 6" 3,000# manual BOP. Test BOP and wellhead to 1,000 psi.
- 5. RIH w/ 6¾" rock bit and 3½" drill collars as possible, drill out cement plug at surface and tag surface casing shoe plug at +/- 665':
 - a) If shoe plug tagged inside surface casing, SI BOP and test surface casing to 500 psi. If casing tests, proceed to #6, otherwise, isolate holes in casing and squeeze with 50 sx C cmt w/ 2% CaCl₂. WOC, tag and pressure-test squeeze to 500 psi.
 - b) If shoe plug tagged below 715', POOH with drill string and RIH with AD-1 packento 685'. Test 7-5/8" surface casing to 500 psi.
- 6. Continue drilling out surface casing shoe plug and cement plug 1,450 1,550' with 6¾" rock bit to top of 4½" casing stub at +/- 1,900'. Circulate hole clean and POOH w/ drill string, RD and release reverse unit.
- 7. RIH w/ mule-shoed sub on workstring to casing stub and attempt to enter casing:
 - a) If 4½" casing is entered, continue in hole and tag cmt plug at +/- 2,337'. Circulate hole with plugging mud and pump 25 sx C cement w/ 2% CaCl₂ at PBTD. WOC and tag this plug to insure minimum of 100' plug at PBTD.

Proposed re-entry/plugs...g procedure Conoco Inc. - State U-5 #3 API #30-015-02908; 1980 FNL & 660 FWL, Unit Letter E, Section 5, T-17-S, R-29-E Eddy County, New Mexico

- b) PUH with tubing to 50' below casing stub and pump 40 sx C cement with 2% CaCl₂. WOC and tag this plug at least 50' above casing stub. Proceed to #8.
- c) If unable to enter 4½" casing, pump 40 sx C cement with 2% CaCl₂ at casing stub. WOC and tag this plug to insure minimum of 100' plug on top of casing stub.
- 8. With tubing at tag above casing stub, circulate hole with plugging mud.
- 9. POOH with tubing to 890' and pump 70 sx C cement with 2% CaCl₂ at 890'. WOC and tag this plug no deeper than 665' to cover top of Yates and surface casing shoe.
- 10. POOH with tubing and ND BOP. RIH with tubing to 50' and circulate cement to surface, estimated 15 sx C cement.
- 11. Cut off wellhead and install dry hole marker. Cut off anchors and close working pit.

¥



