

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
TO THE DISTRICT OFFICE
WITH LOG

FORM APPROVED
Budget Number No. 42 H1424
LEASE DESIGNATION AND SERIAL NO.

LC-028784-b

C. IN INDIAN, ALLOTTEE OF TRUST NAME

SUNDRY NOTICES AND REPORTS ON WELLS

USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT PERFORATION
USE "APPLICATION FOR PERMIT" FOR SUCH PROPOSALS

1. ☒ WELL ☐ CAS. WELL ☐ OTHER

2. NAME OF OPERATOR

General American Oil Company of Texas

3. ADDRESS OF OPERATOR

P. O. Box 128 Loco Hills, New Mexico 88255

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements*)

See also space 17 below
At surface

1980' FSL and 1980' FEL

14. PERMIT NO.

15. ELEVATION (Show whether DT, RT, CR, etc.)

3575' GR

Sec. 26, T-17S, R-29E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FEATHER TREAT ☐

SHOOT OR ACIDIZE ☐

FEATHER WELL ☐

(Other)

PULL OR ALTER Casing ☐

MULTIPLE COMPLETION ☐

ABANDON* ☐

CHANGE PLANK ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FEATHER TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING Casing ☐

ABANDONMENT* ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The following work was completed June 24 — 29, 1981:

1. Spot 25 sacks cement to plug off perforations 1232'-1224'.
2. Ran casing stretch survey to confirm 7" casing free as shown on the Cement Bond Log.
3. Using string shot, backed off casing at first free collar (820'), and pull 7" casing out of hole.
4. Spot 150' cement plug to cover Base of Salt (785') and casing stub (820'). Top of plug @ 720'.
5. Spot 100' cement plug over 8-5/8" casing shoe @ 411'. Top of plug @ 364'.
6. Set 10 sack surface plug.
7. Install permanent dry hole marker.

Additional report will be submitted at end of 4 well abandonment program.

18. I hereby certify that the foregoing is true and correct

SIGNED M. S. Lanning

TITLE Engineer

DATE June 30, 1981

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: