

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

015F

5. LEASE DESIGNATION AND SERIAL NO.

LC-028775-B

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

6. IF INDIAN, ALLEGE OR TRIBE NAME

88210

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. UNIT AGREEMENT NAME

Robinson Jackson Unit

2. NAME OF OPERATOR

Southland Royalty Company

8. FARM OR LEASE NAME

RJU Tract 2A

3. ADDRESS OF OPERATOR

P.O. Box 51810, Midland, TX 79710-1810

3a. AREA CODE & PHONE NO.

(915)688-6800

9. WELL NO.

9

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface
660' FSL & 1980' FWL
1980

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson 7R,QN

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

29
Sec 34, 17S, 29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3530' GL

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. POH w/rods and pump. LD same. Install BOPE. POH w/2-3/8" tubing.

RIH w/2 7/8" tubing and bit to +/-2740'. POH. RIH w/gauge ring and junk basket on sandline to +/-2725'.

RIH w/7"-20# CIGR and set @ +/- 2718'. Test tubing to 1500 psi. Cement sq. Grayburg Jackson open hole interval w/50 sxs Class C. Pull out of retainer and dump 6 sxs Class C atop same. Displace hole w/10ppg gelled brine. POH.

RIH w/7" CIBP and set @ +/- 2385'. Lay 25 sxs Class C CMT atop CIBP. POH.

RIH w/4" casing gun and perforate from 725'-726' w/4 jhpf (8 holes). POH. RIH w/ 7" CIGR and set at +/- 850'. Test tubing to 1000 psi.

RU cementing equipment. Establish injection rate with fresh water. Cement squeeze below retainer w/ 30 sx Class C cement. Pull out of retainer and dump 6 sx Class C cement atop retainer. POH.

RIH w/4" casing gun and perforate 386'-387' w/4 JHPF (8 holes).

ND BOPE. RU cementing equipment. Establish circulation down 7" casing w/fresh water. Mix and pump 150 sxs Class C cement and circulate to surface.

Cut off casing 3' below surface and place abandonment maker as per regulations.

Restore location as directed.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Asst.

DATE

(This space for Federal or State office use)

APPROVED BY

(ORIG. SGD) DAVID R. GLASS

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SEE ATTACHED

*See Instructions on Reverse Side