				_		
10. OF COPIES RECEIVED					orm C-103	
DISTRIBUTION				Say	upersedes Old	
SANTA FE	NEW MEX	ICO OIL CON	ERVATION COMMISSION	Ef	-102 and C-103 ffective 1-1-65	
FILE		Ī			1-1-05	
U.G.G.S.				Sg. Inc	dicate Type of Lease	
LAND OFFICE			25 4 C		ate X	
OPERATOR	+1			L		Fee
	J			5, 5(a)	te Oil & Gas Lease N	lo.
					<u>B-514</u>	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT " (FORM C-101) FOR SUCH PROPOSALS.)						
OIL C GAB	COTHER-			7. Uni	t Agreement Name	
2. Liame of Operator	7	· · ·	······································	8. Far	m or Lease Name	
Company Compan	ny				J West Coop (Init
Box 1031, Midland	<u>l, Texas 79701</u>				10	
Ŧ	1000			10, Fie	eld and Pool, or Wilde	
UNIT LETTER	FEET FROM T	<u>south</u>	LINE AND 660 FEE	T FROM Gra	ayourg-Jackso	n
					<u>IIIIIIIIII</u>	TUUT
THE West LINE, S	ECTION <u>28</u> TOW	NSHIP 17-5	RANGE 29-F		///////////////////////////////////////	//////
					///////////////////////////////////////	11111
	15. Elevation	n (Show whether	DF, RT, GR, etc.)	12. Co	unty All	HHH
		35	70 GR	Edd		/////
16. Che	ck Appropriate Boy T					\overline{m}
NOTICE O	F INTENTION TO:	o marcate in	ature of Notice, Report o subseq	OF Other Dat		
PERFORM REMEDIAL WORK						
THE OR A CHALWORK	PLUG AN			VI.		
TEMPORARILY ABANDON	PLUG AN	D ABANDON	REMEDIAL WORK	X	ALTERING CASING	
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.		ALTERING CASING Plug and Abandon	MENT
	PLUG AN Change					MENT
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.			MENT
TEMPORARILY ABANDON	CHANGE	PLANS	COMMENCE DRILLING OPNS. Casing test and cement Job Other		PLUG AND ABANDON	
TEMPORARILY ABANDON	CHANGE	PLANS	COMMENCE DRILLING OPNS. Casing test and cement Job Other	Luding estimated	PLUG AND ABANDON	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE 1103. PROCEDURE:	CHANGE	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc	Luding estimated	PLUG AND ABANDON	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE 1103. PROCEDURE: 1. Pulled and lai. 2. Perforated wit, 2429, 2443, 244	CHANGE d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc off pulling unit. 23.32, 2337, 2341, 2 26.52, 2607, 2647		PLUG AND ABANDON	proposed
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE' 1 fos. PROCEDURE: 1. Pulled and lai. 2. Perforated wit: 2429, 2443, 244 on wire line a: 3. Frac down csg.	CHANGE Ad Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.02, 2607, 2617. i avid down 0.36.	2357, 2369 Set retri	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridge	proposed
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE 1103. PROCEDURE: 1. Pulled and lai. 2. Perforated wit: 2429, 2443, 244 on wire line a:	CHANGE Ad Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc off pulling unit. 23.32, 2337, 2341, 2 26.52, 2607, 2647	2357, 2369 Set retri	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridge	proposed
 TEMPORARILY ABANDON PULL OR ALTER CASING OTHER OTHER I. Describe Proposed or Complete work) SEE RULE 1103. PROCEDURE: I. Pulled and lai. 2. Perforated wit: 2429, 2443, 244 on wire line a: 3. Frac down csg. 	CHANGE d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.02, 2607, 2617. i avid down 0.36.	2357, 2369 Set retri	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridge	proposed
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE 1103. PROCEDURE: 1. Pulled and lai. 2. Perforated wit: 2429, 2443, 244 on wire line a: 3. Frac down csg. 10 BW. 4. Shut-in overnig	CHANGE d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo ght.	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER Us, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.)2, 2607, 2617. I avid down 0.3g. Water and 75,000# 2	2357, 2369 Set retri 20-40 sand	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridg . Overflushe	proposed
 TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE 1103. PROCEDURE: PROCEDURE: Pulled and laid Perforated with 2429, 2443, 244 on wire line at Frac down esg. 10 BW. Shut-in overnig 5. Bled off pressure 	change d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo ght. ure, ran tbg. w/re	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.02, 2607, 2617. i avid down 0.36.	2357, 2369 Set retri 20-40 sand	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridg . Overflushe	proposed
 TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE' 1703. PROCEDURE: PROCEDURE: Pulled and laid Perforated with 2429, 2443, 244 on wire line at Frac down esg. 10 BW. Shut-in overnig 5. Bled off pressure 	CHANGE d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo ght.	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER Us, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.)2, 2607, 2617. I avid down 0.3g. Water and 75,000# 2	2357, 2369 Set retri 20-40 sand	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridg . Overflushe	proposed
 TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Complete work) SEE RULE 1703. PROCEDURE: 1. Pulled and laid 2. Perforated with 2429, 2443, 244 on wire line at 3. Frac down esg. 10 BW. 4. Shut-in overnig 5. Bled off pressure 	change d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo ght. ure, ran tbg. w/re	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER Us, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.)2, 2607, 2617. I avid down 0.3g. Water and 75,000# 2	2357, 2369 Set retri 20-40 sand	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridg . Overflushe	proposed
 TEMPORARILY ABANDON PULL OR ALTER CASING OTHER OTHER I. Describe Proposed or Complete work) SEE RULE 1103. PROCEDURE: PROCEDURE: Pulled and laid Perforated with 2429, 2443, 244 on wire line at Frac down esg. 10 BW. Shut-in overnig Bled off pressu Ran tbg. and ro 	change d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo ght. ure, ran tbg. w/re ods and put on pum	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.02, 2607, 2617. I avid down 0.3g. Water and 75,000# 2 head and recovered b	2357, 2369 Set retri 20-40 sand	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridg . Overflushe	proposed
 TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE' 1703. PROCEDURE: PROCEDURE: Pulled and laid Perforated with 2429, 2443, 244 on wire line at Frac down csg. 10 BW. Shut-in overnig Bled off pressu Ran tbg. and rook 	change d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo ght. ure, ran tbg. w/re ods and put on pum	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.02, 2607, 2617. I avid down 0.3g. Water and 75,000# 2 head and recovered b	2357, 2369 Set retri 20-40 sand	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridg . Overflushe	proposed
 TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE' 1703. PROCEDURE: PROCEDURE: Pulled and laid Perforated with 2429, 2443, 244 on wire line at Frac down csg. 10 BW. Shut-in overnig Bled off pressu Ran tbg. and ro 	change d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo ght. ure, ran tbg. w/re ods and put on pum	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.02, 2607, 2617. I avid down 0.3g. Water and 75,000# 2 head and recovered b	2357, 2369 Set retri 20-40 sand pridge plu	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridg . Overflushe	proposed
 TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Complete work) SEE RULE' 1703. PROCEDURE: PROCEDURE: Pulled and laid Perforated with 2429, 2443, 244 on wire line at Frac down csg. 10 BW. Shut-in overnig Bled off pressu Ran tbg. and rook 	change d Operations (Clearly state of d down rods and th h one 3/8" jet, 23 48, 2457, 2467, 24 t 2645. Dumped 50 with 50,000 gallo ght. ure, ran tbg. w/re ods and put on pum	PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ils, and give pertinent dates, inc of? pulling unit. 23.32, 2337, 2341, 2 26.02, 2607, 2617. I avid down 0.3g. Water and 75,000# 2 mead and recovered b	2357, 2369 Set retri 20-40 sand pridge plu	PLUG AND ABANDON d date of starting any 9, 2384, 2402 evable bridge . Overflushe g.	proposed

1

•

e.

i