

30-015-04178

<u>Est. Geol. Tops per Bq</u>	
Rustbr 250	Queen 2100
Salado 560	Grayburg 2500
B salt 1025	San Andres 2800
Gates 1200	
TRivers 1510	
Bowers 1825	

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87401

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO.
30-015-04178

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2130

7. Lease Name or Unit Agreement Name
Randel State

8. Well No.
2

9. Pool name or Wildcat
Grbg Jackson SR Q Grbg SA

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDY NOTICES REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSED DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Mack Energy Corporation /

3. Address of Operator
P.O. Box 960, Artesia, NM 88211-0960

4. Well Location
Unit Letter D : 990 Feet From The North Line and 990 Feet From The West Line
Section 16 Township 17S Range 30E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug and abandon well as follows:

1. Notify OCD 24 hours prior to starting plugging operations.
2. RIH tag CIBP @ 1988' set 35' cement cap.
3. Set ~~25'~~ plug ~~3'~~ above and below bottom of salt from 1000-1025'.
4. Set ~~50'~~ plug 50' above and below 8 5/8 casing from 550-450'.
5. Set ~~10'~~ surface plug.
6. Install dry hole marker.

Salt gel mud consisting of 10#
Brine W/25# of gel per bbl
must be placed between each plug

Perf csq @ 1125'. Place 100' of cmt.
inside & outside of csq. 1025'-1125' - TAG

Perf csq @ 550'. Place 100' of cmt.
inside & outside of csq. 450'-550' - TAG

Perf Both 8 5/8" & 7" csq. @ 60'.
Place 60' of cmt. inside & outside of
Both strings of csq.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Crissa D. Carter TITLE Production Analyst DATE 10/21/02

TYPE OR PRINT NAME

Crissa D. Carter

TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE OCT 28 2002

CONDITIONS OF APPROVAL, IF ANY