

**ENRON OIL AND GAS COMPANY**  
**McIntyre A No. 6**  
**990' FSL & 1650' FEL**  
**Section 20, T17S, R30E**  
**Eddy County, New Mexico**

**PROCEDURE TO P&A**

1. MIRU single drum unit.
2. Pick up 2-7/8" D.P. w/crooked joint on bottom w/ 6-1/8" Bowen series 150SFS overshot w/  $\pm$  4' extension dressed for 4-1/2" casing w/top sub dressed w/ 2-1/2" mod pin down.
3. Make runs as required to recover 4-1/2" casing to  $\pm$  4,050' or a good casing top above 4,000'. Top of tubing @ 4,012'. If casing is recovered below 4,012' without having a good casing top go to step 5.
4. Put 4-1/2" casing together w/4-1/2" casing and full ID overshot. Hang casing on slips and cut off.
5. Make runs as required to recover 2-3/8" tubing at top of packer.
6. If packer cannot be released and pulled, cut off tubing as close to packer as possible. POH w/same.
7. Run gauge ring and set 4-1/2" CIBP at 11,000' or on top of tubing stub. Dump  $\pm$  50' cement on top of CIBP w/bailer. Optional 200' cement plug thru tubing.
8. Pick up 4-1/2" casing string and find free point. Cut off 4-1/2" casing.
9. Lay down 4-1/2" casing.
10. Pick up 2-3/8" tubing and set cement plugs per regulatory requirements.
11. All mud will be 9.0#/gal. brine with 25#/bbl gel. 25 SACKS GEL PER 100 BBLS OF WATER.
12. Notify BLM Carlsbad (505)887-6544 24 hours prior to starting job.