

*Attachment to Form 3160-5*

**MCINTYRE "G" FEDERAL #1  
WORKOVER PROCEDURE  
FOR CASING INTEGRITY**

**8-18-92**

1. MIRU pulling unit.
2. RU wireline unit. TIH w/ tbg. cutter. Cut tbg. at 2015' and POOH.
3. TIH with bit and scraper to TOF. POOH.
4. TIH with cmt. retainer and tbg. testing tbg. to 5000 psi. Set retainer at 2010'.
5. Load tbg. and establish pump-in rate and pressure with water. Squeeze with 500 sx class C neat. Pull out of retainer, reverse out and WOC 6 hrs. Sting back into retainer and test to 1000 psi.
6. If squeeze test is satisfactory, test casing to 500 psi. Pull out of the retainer and spot 20'  
50' cmt. on top of the retainer. POOH.
7. Shut in well pending geological and engineering evaluation and partnership approval (if well is to be shut in for more than 30 days, file intent to temporarily abandon).