

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other instructi
verse side)DATE
on reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029020(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Shut In Water Injection Well <input checked="" type="checkbox"/>	7. UNIT AGREEMENT NAME Grayburg Jackson
2. NAME OF OPERATOR General Operating Company	8. FARM OR LEASE NAME Tract 3 Well No. 3
3. ADDRESS OF OPERATOR P. O. Box 877, Wichita Falls, Texas 76307	9. WELL NO. 23-T17S-R30E
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1750' FSL and 330' FWL Section 23-T17S-R30E	10. FIELD AND POOL, OR WILDCAT Grayburg Jackson
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 23-T17S-R30E	12. COUNTY OR PARISH Eddy
13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

General Operating Company proposes to plug and abandon the captioned shut in water injection well as follows:

- (1) Set cast iron bridge plug at 3050' in 5½" OD, 14# liner immediately above liner perforations from 3073'-94'. 5½" OD liner set from 2722'-3120' and cemented top to bottom with 250 sacks.
- (2) Dump 35' cement plug on top of bridge plug.
- (3) Shoot off 7" OD, 26#, J-55 long string of casing at first free point. 7" OD casing set at 2788' and cemented with unknown quantity of cement. Estimated free point 2000'.
- (4) Pump 100' cement plugs with mud laden fluid between plugs through 2" tubing as follows:
 - (a) Over 7" OD casing stub.
 - (b) Over base salt from 1150'-1250'.
 - (c) Over 10-3/4" OD surface casing seat from 450'-550'.
 - (d) Over 10-3/4" OD surface casing stub if any is pulled.
- (5) Dump 20' surface cement plug in surface casing with cement outside of surface casing if no surface casing is pulled.
- (6) Set surface marker, fill pit, and clean up location.

18. I hereby certify that the foregoing is true and correct

SIGNED

C. W. Stamboloff

TITLE

Partner

DATE

June 3, 1974

(This space for Federal or State office use)

APPROVED BY

SIGNATURE OF APPROVAL IF ANY:

TITLE

DATE

*See Instructions on Reverse Side