

N. M. O. C. G. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI
(Other instructions
verse side)TE*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-059376

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

Grayburg Jackson Unit

8. FARM OR LEASE NAME

-

9. WELL NO.

Tract 11 Well No. 2

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., M., OR BLEK. AND
SURVEY OR AREA

27-T17S-R30E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

JUL 25 1974

1. OIL WELL ☒ GAS WELL ☐ OTHER Shut In

2. NAME OF OPERATOR

General Operating Company

3. ADDRESS OF OPERATOR

P. O. Box 877, Wichita Falls, Texas 76305

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface660' FNL and 660' FEL
Section 27-T17S-R30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3641' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

General Operating Company proposes to plug and abandon the captioned shut in oil well as follows:

- (1) Set cast iron bridge plug at 3150' in 4½" OD, 10.5# liner immediately above liner perforations from 3183'-95'. 4½" OD liner set from 2955'-3222' and cemented top to bottom with 150 sacks.
- (2) Dump 35' cement plug on top of bridge plug.
- (3) Shoot off 7" OD, 20# long string of casing at first free point. 7" OD casing set at 3001' and cemented with 100 sacks. Estimated free point 1500'-2000'.
- (4) Pump 100' cement plugs with mud laden fluid between plugs through 2" tubing as follows:
 - (a) Over 7" OD casing stub.
 - (b) Over base salt from 1160'-1260'.
 - (c) Over 8-5/8" OD surface casing seat from 440'-540'.
 - (d) Over 8-5/8" OD surface casing stub if any is pulled.8-5/8" OD, 24# surface casing set at 490' cemented with 50 sacks.
- (5) Dump 20' surface cement plug in surface casing with cement outside of surface casing if no surface casing is pulled.
- (6) Set surface marker, fill pit, and clean up location.

18. I hereby certify that the foregoing is true and correct

SIGNED

C. W. Stumpp

TITLE

PARTNER

DATE JUNE 17, 1974

(This space for Federal or State office use)

TITLE

DATE

APPROVED BY
CONDITION OF APPROVAL, IF ANY:

JUL 25 1974

R. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side