

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different well zone. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR Anadarko Production Company	3. ADDRESS OF OPERATOR P. O. Drawer 130, Artesia, New Mexico 88210	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FNL & 990' FWL	5. PERMIT NO.	6. ELEVATIONS (Show whether DF, RT, GR, etc.) Not available	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME Federal "S"	9. WELL NO. 5	10. FIELD AND POOL, OR WILDCAT Fren-7 Rivers	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 28 - 17S - 30E	12. COUNTY OR PARISH Eddy	13. STATE New Mexico
--	--	---	---	---------------	--	------------------------	--------------------------------------	------------------	---	--	------------------------------	-------------------------

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	Plug & Abandon	(Other)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. RUPU; TIH with tubing to PBTD of 1878'.
2. Circulate hole with 10# brine and salt gel mud.
3. Spot 40 sx Class H cement with 6% CaCl from 1878' to 1743' - to cover 7-Rivers top @ 1820'.
4. Pull tubing up hole; WOC 3 hours; tag top of plug.
5. Spot 40 sx Class H cement with 6% CaCl from 1270' to 1135' - to isolate bottom of Salt.
6. Pull tubing up hole; WOC 3 hours; tag top of plug.
7. Spot 40 sx Class H cement with 6% CaCl from 500' to 365' - to cover 8-5/8" casing shoe and isolate top of Salt section.
8. Pull tubing up hole; WOC 3 hours; tag top of plug.
9. Spot Class H cement with 6% CaCl from 50' to surface; TOH - this will cover surface plug.
10. RDPUP; cut off all casing and anchors below surface; set P & A marker; clean and level location.

Note: There will be 10# brine and salt gel mud between all plugs.

I hereby certify that the foregoing is true and correct

SIGNED M. B. Brwell TITLE Field Foreman DATE January 11, 1985

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 1-23-85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Feel S #5

Anadarko 