

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☒ - Water Injection well
2. NAME OF OPERATOR
Anadarko Production Company
3. ADDRESS OF OPERATOR
P. O. Drawer 130, Artesia, New Mexico 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1650' FSL & 2310' FEL
AT TOP PROD. INTERVAL: Same Sec. 31, T17S, R30E
AT TOTAL DEPTH: Same Eddy County, New Mex.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) _____

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED BY

OCT 17 1983

O. C. D.
ARTESIA, OFFICE

5. LEASE

LC 028936-D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal M

9. WELL NO.

2

10. FIELD OR WILDCAT NAME

Loco Hills-Queen-Grayburg-San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

31 - 17S - 30E

12. COUNTY OR PARISH

Eddy

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3571' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Move in, rig up pulling unit.
- Pump brine gel mix @ 25# gel/bbl of 10# brine from PBTD 2900' to surface.
- Spot 200' Class C cement with 3% CaCl 100' above & 100' below Grayburg top @ 2688'.
- GIH with perf guns & tag top of 1st plug; pull up & perf 4 holes @ 1220' (100' below Salt section).
- Spot 200' cement from 1220' to 1020' & squeeze half of plug out squeeze holes.
- GIH with perf guns & tag top of 2nd plug; pull up & perf 4 holes @ 510' (top of Salt section).
- Circulate cement down 7" casing out holes @ 510' & up 8-5/8" casing to surface.
Note: This plug will cover top of Salt section and also serve as surface plug.
- Cut off all casing & anchors below surface; set P & A marker; clean & level location.
Note: See Item #7 - If cannot establish circulation to surface, will spot 200' cement plug from 510' to 310' and squeeze half of plug out perfs; tag plug with wireline & set 10" plug @ surface.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Mike Braswell TITLE Field Foreman DATE September 20, 1983

APPROVED

(This space for Federal or State office use)

(Off. Sec.) PETER W. CHESTER

TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OCT 13 1983