

45F

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other X-Water Injection Well

2. NAME OF OPERATOR
Anadarko Production Company

3. ADDRESS OF OPERATOR
P. O. Drawer 130, Artesia, New Mexico 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2310' FNL & 2310' FWL
AT TOP PROD. INTERVAL: Same Sec. 31, T17S, R30E
AT TOTAL DEPTH: Same Eddy County, N.Mex.

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF
- FRACTURE TREAT
- SHOOT OR ACIDIZE
- REPAIR WELL
- PULL OR ALTER CASING
- MULTIPLE COMPLETE
- CHANGE ZONES
- ABANDON*
- (other) _____

SUBSEQUENT REPORT OF:

-
-
-
-
-
-
-
-

RECEIVED BY
OCT 13 1983
O. C. D.
ARTESIA OFFICE

5. LEASE
LC 028936-D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal L

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Loco Hills-Queen-Grayburg-San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
31 - 17S - 30E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3552' GL

NOTE: Report results of multiple completion or zone change on Form 9-330.

RECEIVED

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in, rig up pulling unit.
2. Pump brine gel mix @ 25# gel/bbl of 10# brine from PBTD 2682' to surface.
3. Set cement retainer 50' above Grayburg Formation top @ 2668' & cement squeeze 200' cement below retainer to cover formation top.
4. GIH with perf guns & perf 4 holes @ 1155' (100' below Salt section).
5. Spot 200' cement from 1155' to 955' & squeeze half of plug out perfs.
6. GIH with perf guns & tag top of 2nd plug; pull up & perf 4 holes @ 530' (top of Salt section).
7. Circulate cement down 7" casing out holes @ 530' & up 8-5/8" casing to surface.
Note: This plug will cover top of Salt section & also serve as surface plug.
8. Cut off all casing and anchors below surface; set P & A marker; clean & level location.
Note: See Item #7 - If cannot establish circulation to surface, will spot 200' cement plug from 530' to 330' & squeeze half of plug out perfs; tag plug with wireline & set a 10 sx plug @ surface.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Mike Braswell TITLE Field Foreman DATE September 20, 1983

APPROVED _____ (This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:
OCT 12 1983