

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ - Water Injection well

2. NAME OF OPERATOR

Anadarko Production Company ✓

3. ADDRESS OF OPERATOR

P. O. Drawer 130, Artesia, New Mexico 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650' FNL & 2537' FWL

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☒

(other) ☐

5. LEASE

LC 028936-D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal L

9. WELL NO.

5

10. FIELD OR WILDCAT NAME

Loco Hills-Queen-Grayburg-San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

31 - 17S - 30E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3565' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Note: This well has been under study for possible deepening & completion in Metex & Premier Zones but Anadarko has now decided to go ahead & P&A the well.

1. Move in and rig up pulling unit.
2. Pump brine gel mix @ 25# gel/bbl of 10# brine from PBTD 2837' to surface.
3. Spot 200' Class C cement with 3% CaCl 100' above & 100' below Grayburg top @ 2640'
4. GIH with perf guns & tag top of 1st plug; pull up & perf 4 holes @ 1132' (100' below Salt section).
5. Spot 200' cement from 1132' to 932' & squeeze half of plug out squeeze holes.
6. GIH with perf guns & tag top of 2nd plug; pull up & perf 4 holes @ 465' (50' above Salt section).
7. Spot 200' cement from 465' to 265' & squeeze half of plug out perfs.
8. Tag plug with wireline and set surface plug from 50' to surface.
9. Cut off all casing & anchors below surface; set P & A marker; clean & level location.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Mike Braswell TITLE Field Foreman DATE March 26, 1984

(This space for Federal or State office use)

APPROVED BY R. Ritzke
CONDITIONS OF APPROVAL, IF ANY:

TITLE P.E.

DATE 6/15/84

Subject	Fed. L# 5	Page No.	01
File		By	JEB
		Date	2-3-82

