10-13-84: Unable to get past 504'. Pmpd 60 sx of Class "C" w/2% CaCl. Did not circ fluid level approx. 15' from surface.

fluid level approx. 15' from surface.
10-19-84: WiH w/l" tbg. Tagged cement at 30' below surface. Tagged witnessed by
BLM. Cemented to surface from 30' with 6 yds of ready mix. (Per approval
from John Wade) Installed dry hole marker. RD, cleaned location.
Well plugged and abandoned.

≥.

including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and

Recommended procedure to plug and abandon:

MI RU DDU. Install BOP. COOH with tubing. GIH with 2-3/8" tubing to 2825'. Displace hole with 9.5 ppg mud laden fluid. Spot 20 sx Class C cement with 2% CaCl₂ mixed @ 14.8 ppg. This plug will fill the open hole interval (2826' -2799') and cover the 5-1/2" csg shoe with a 100' plug. Pull up to 2000', reverse circulate tubing clean and COOH. WOC, tag cmt. 302 22

Weld pull nipple on 5-1/2" casing. Run freepoint by stretch method, cut and pull casing.

GIH w/2-3/8" workstring tubing to the lesser of 1150' or 50' below casing cut off point and spot 50 sx Class C cement w/2% CaCl2. Displace cement w/9.5 ppg mud laden fluid. Pull up to 600', reverse circulate tubing clean. SEE LEVERSE SIDE

Subsurfage S

Safety Valve: Manu. and TypeN/A	Set @ Ft	
safety varve, manus and type		
centify that the foregoing is true and correct		

18./I hereby

SIGNED THE	W. J. Mueller TITLE Sr. Engineering	DATE	August	22,	1984
SIGNED	Specialist		La s		
	(This ages for Endam) or State office use)		- L		<u></u> .

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

TOC to be a minimum of 1050' or 50' above the casing cut if the casing was cut shallower than 1100'. WOC, tag TOC. Pull tubing to 580' and spot 220 sx of Class C cement with 2% CaCl $_2$ to surface. Cut off CHF. Weld on 1/2" plate for abandonment. Fill in hole and clean surface.

BOP EQUIP: Series 900, 3000# WP double w/l set pipe rams, l set blind rams, manually operated.