

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NM OILS & GAS DIVISION
(Other instruction on reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED BY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.) JUL 5 1985		5. LEASE DESIGNATION AND SERIAL NO. N. M. 0467931 C/SF	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
7. UNIT AGREEMENT NAME			
8. FARM OR LEASE NAME Federal R			
9. WELL NO. 4			
10. FIELD AND POOL, OR WILDCAT Square Lake-Grayburg-SA			
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 10 - 17S - 30E			
12. COUNTY OR PARISH Eddy		13. STATE New Mexico	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3715' GL	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Repair Casing

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Note: This Federal WIW recently failed NMOCD scheduled "Casing Integrity Test". This work is scheduled to satisfy Mike Williams' (NMOCD) letter to Anadarko dated June 6, 1985 requesting that repairs be made within 30 days.

1. Rig up pulling unit; pull tubing and packer.
2. Use packer & retrievable bridge plug to determine the general condition of the casing (location & extent of holes).
3. We will then consult with NMOCD representative to determine a satisfactory method of repair (which probably will consist of one or more of the following):
 - (A) Back off casing and replace upper joints if hole is shallow.
 - (B) Circulate cement or cement squeeze casing if replacement isn't practical.
 - (C) Cement another string of casing in the well after determining the Salt to be isolated.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supervisor

DATE

June 11, 1985

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

7-2-85

CONDITIONS OF APPROVAL, IF ANY:

**Subject to
Like Approval**

*See Instructions on Reverse Side