## JED STATES

DEPARTMENT OF THE INTERIOR (Other instructions on re-			Budget Bures	Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.	
			LC-029418(b)		
CLINIDDY	<del></del>	>>1 \\/ELLC	6. IF INDIAN, ALLOTTE		
	NOTICES AND REPORTS O				
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)					
1.		RECEIVEL	7. UNIT AGRBEMENT NA	ME	
WELL GAS WELL G	OTHER	EIVE			
2. NAME OF OPERATOR	2		8. FARM OR LEASE NAM	<b>a</b>	
Skelly 011 Com	pany	- JUN 6 1070	Les Reif		
3. ADDRESS OF OPERATOR		19/2	9. WELL NO.	-	
P. O. Box 1351	, Midland, Texas 79701	<b>~</b> -	9		
4. LOCATION OF WELL (Report lo See also space 17 below.)	ocation clearly and in accordance with any	State requirements.	10. FIELD AND POOL, OF	K WILDCAT	
At surface		BARRICE .	Gravburg-J	ackson	
			SEC., T., B., M., OR E		
		11.4 mg	SURTES OR ARBA	en e	
660' FSL and 1980	' FWL, Sec. 11-178-31E	94N - 5 1922	Sec. 11-17	5-31 E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc. S	12. COUNTY OR PARISH	13. STATE	
	3942' 1	DP 481 State Control	Eddy	New Mexico	
.6. CL.	I A . D T I I . N	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	14. V	-	
Che	eck Appropriate Box To Indicate N	ature of Notice, Report, or	Other Data:	- ·	
NOTICE (	OF INTENTION TO:	SUBSEC	QUENT REPORT OF:	* 1	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING V	FELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	AETERING CA	ļ—-	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN		
REPAIR WELL	CHANGE PLANS	(Other) Set 5-1/2"	casing, perf.	X trea	
(Other)	<u> </u>	(Note: Report result	s of multiple completion operation Report and Log for	on Well	
<ol><li>Cemented casing per sack; and</li></ol>	e packer set at 2716'. g with 1000 sacks Trinity 300 sacks Class "C" with 2	Light Weight with 1, 2 calcium chloride.	/24 cellofiakes Pumped plug to	and 10# sal 3920'. Ce	
	i. WOC 18 hours.				
	casing to 1500# for 30 min	utes; held OK.		•	
	Neutron log 2000-3912'.				
6) Spotted 500 gal	ls. 15% acid in 5-1/2" OD	casing 3878-3369'.	2		
7) Perforated 5-1/	2" casing with one 3/8" s	hot at: 3369', 339	3 <b>',</b> 34 <b>50',</b> 3497'	3514	
3544', 3557', 3	3606', 3622', 3636', 3696'	', 3742', 3768', 3778	8', 3820', 3842'	', 3858', and	
	over 509' interval.)				
8) Set packer at 3	3300' and treated above pe	rfs. with 2250 gals	. 15% ME acid at	nd 40 ball	
	ned with 38 bbls. lease we	iter.			
9) Swabbed, recove				$\tilde{\mathbf{x}} = \tilde{\mathbf{x}}_{1} + \tilde{\mathbf{x}}_{2}$	
(0) Treated above	perfs. down casing with 35	,000 gals. 9# gelled	i brine weter;	2,000# 20/4	
send and two 7/	8" ball sealers. Flushed	with 100 bbls. wate	er. abatas I		
1) Set 125 jts. (1	3878') of 2-3/8" OD tubing	at 3890'; mud ancho	or 3859-3890 <sup>3</sup> ; p	erf. nipple	
	ing nipple 3855-56'.				
.2) Ran rods, set p	oump at 3855' and commence	d testing.			
			<u> </u>		
8. I hereby certify that the fore					
signed (Signed	O. P. Cross TITLE Les	d Clerk	DATE June 1	, 1972	
			DATE		
(This space for Federal of	tate office use)				
ADDROVED TO THE	TITLE		T A Min	<u> </u>	
OVERTIONS OF APPROVA			DATE		