Form 3160-5 (November 1983) (Formerly 9-331)	UNICOS EPARTMEN. OF BUREAU OF LAND	THE INT		5. LEASE DESIGNATION AN	1. 1985	
SUNDR (Do not use this form	Y NOTICES AND	REPORT		LC-029420-B 6. IF INDIAN, ALLOTTEE O	OR TRIBE NAME	
I. OIL X GAS WELL OTHER				7. UNIT AGREEMENT NAME		
				Skelly Unit		
Texaco Producing	Inc.			8. FARM OR LEASE NAME		
3. ADDRESS OF OPERATOR				Skelly Unit		
P.O. Box 730, Ho	bbs, NM 88240			151		
4. LOCATION OF WELL (Repor See also space 17 below.) At surface	t location clearly and in acc	ordance with	any State requirements.	10. FIELD AND POOL, OR V	WILDCAT	
At surrace	1970			Fren Seven Riv		
Letter K, 2130'	FSL & 1988' FWL			11. SEC., T., R., M., OR BLE SURVEY OR ARMA		
14. PERMIT NO. 15. ELEVATIONS (Show 38		3860	· · · · · · · · · · · · · · · · · · ·	Sec. 15, T-17- 12. COUNTY OR PARISH 1 Eddy	S, K-31-E 8. STATE NM	
16.	heck Appropriate Box	To Indica	te Nature of Notice, Report, or C	<u>-</u>	1411	
	E OF INTENTION TO:	· · · · · · · · · · · · · · · · · · ·		URNT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER C			JENT REPORT OF:	 1	
PRACTURE TREAT	MULTIPLE COMPL		WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WEL		
SHOOT OR ACIDIZE	ABANDON*	X	SHOOTING OR ACIDIZING	ABANDONMENT®		
REPAIR WELL (Other)	CHANGE PLANS		(Other)	of multiple completion on		
SEE ATTACHMENT		,				
			RECEIVED	OAREA HEA	LLI.	
			JUL 27 '90	10 10 00 00 00 00 00 00 00 00 00 00 00 0	. X	
			O. C. D ARPESIA OFFICE	AM '90	. 0	
18. I hereby certify that the fo	earl/RJ8	TITLE _	Area Manager	DATE 07/20/	90	
(This space for Federal or Ong. Sign APPROVED BY		TITLE _	SECONOMIC SECONDER	DATE 125	90	
CONDITIONS OF APPROV	AL, IF ANY:					

SKELLY UNIT WELL NO. 151 Proposed Plugging Procedure

1) Backflow well.

2) Inform BLM 24 hrs. prior to commencement of work.

- 3) MIRU pulling unit. Pull rods and pump. Install BOP. tubing.
- 4) By wireline. RIH with CIBP and set at 2270'. Cap with 35' of cement using a dump bailer.
- 5) RIH with tubing to PBTD. Load hole with salt gel mud consisting of 10 lb. brine with 25 lbs. of gel per barrel.
- 6) Pull up and spot a 25 sx plug of Class "C" cement (1.32 cuft/sx)
- from 1825'-1640' (base of salt 1640'). Tag plug.
 7) Pull up and spot a 25 sx plug of Class "C" cement (1.32 cuft/sx) from 635'-450' (top of salt 630', surface casing shoe at 582'). Tag plug.
- 8) Pull up and pump 7 sx of Class "C" cement (1.32 cuft/sx) from 50'-surface.
- 9) Cut off wellhead. Install marker. Clean location.



