

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)
Artesia, NM 88210

Budget Bureau No. 1004-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

ON NM-0397623

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal KL-17

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Under So. Empire (Atoka)

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 17, T17S, R29E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

Use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

1. WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

7990 IH 10 West, San Antonio, TX 78230

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below

At surface 1840' FNL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3623' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- D. H. Commingling*
Morrow & Atoka
1. Shut down production equipment. Bleed pressure off lines.
 2. MIRU workover rig.
 3. RU kill truck and kill well with 3% KCL, 9.0 ppg, approx. 40 bbls. Monitor well and make sure tubing side is dead. Set BPV in B02 coupling. ND tree.
 4. NU 7 1/16"-5M hydraulic BOP, B/R on top, P/R on bottom - 2 3/8". Have gate valve and manual choke on bottom outlet of BOP. Run 2" line from choke to burn pit.
 5. Release packer. Circulate and condition hole with 9.0 ppg fluid. Drop standing valve. Test tubing to 5000 psi. Retrieve tool. POOH with packer and tubing. Strap out of hole. NOTE: 1 full joint + 2 pups below wrap-around. Send wrap-around to WKM for repair if necessary. Send packer to Baker for redressing.
 6. PU 5 1/2", 17# retrievable BP. RIH to 10,450'+/- . Set same and test to 1500 psi.
 7. POOH to 10,310'. Spot 42 gallons of Morrow type acid from 10,310-10,270'. FPOOH.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Drilling Engineer

DATE

8/25/86

(This space for Federal or State office use)

Orig. Sgd. Charles S. Dillion

APPROVED BY

TITLE

DATE

9/3/86

CONDITIONS OF APPROVAL, IF ANY:

Subject to
Like Approval
by State

*See Instructions on Reverse Side

Tit
Box

It makes it a crime for any person knowingly and willfully to make to any department or agency of the
fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

1. The first step in the process of creating a new product is to identify a market need. This involves conducting market research to determine what consumers want and need. Once a need is identified, the next step is to develop a concept for a product that meets that need. This is often done through brainstorming and prototyping. The third step is to create a business plan that outlines the costs and potential revenue of the product. Finally, the product is manufactured and marketed to the target audience.