Form 3160-5 (November 1983) (Formerly 9-331)

UNITEL STATES **DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT**

(Other Instructions on reverse side)

OII CONS.
N.M. DIV-Dist. 2

SUBMIT IN TRIPLICATE 301 Wige Grand Avenue

(Other Instructions on

					DESIGNATION AND SEI DADO A	RIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS				LC-029420-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
(Do not use this form for proposals to drill or to deepen or p ug back to a different reservoir.				V. II. II. II.	a, razor i de ok i ki	DE NAME
Use "APPLICATION FOR PERMIT - " for such proposals.)					·	
OIL GAS OTHER WELL OTHER				7. UNIT AGREEMENT NAME Skelly Unit		
The Wiser Oil Company				189		
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs New Mexico 88241				API WELL NO.		
-13. 25.05 110505, 110W 110A100 002.11				2 30-015-29206		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. RECEIVED See also space 17 below.)				10. FIELD AND POOL, OR WILDCAT		
At surface (AT 1851A				Grayburg Jackson 7-Rivers-QN-GB-SA		
2630' FSI & 1310' FWI				M. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
Unit L				Sec. 15-T17S-R31E		
14. PERMIT NO 15 ELEVATIONS (Show whether DE RT GR. etc.)						
14. PERMII NO	15. ELEVATIONS (Show wheth 3872'	er DF, R	T, GR, etc.)		TY OR PARISH	13. STATE
16. Check A	Innropriate Roy to indicate	Moturo	of Notice Depart on Other		County	NM
16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:		
TEST WATER SHUT OFF	PULL OR ALTER CASING	7	WATER SHUT-OFF	[]	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING		ABANDONMENT *	
REPAIR WELL	CHANGE PLANS	- ,	(Other)			
	CHANGETEANS	_	(Other)(Note: Report results of	multiple com	pletion on Well	<u> </u>
(Other)			Completion or Recompletion Report and Log form.)			
17. DESCRIBE PROPOSED OR COMPLET: proposed work. If well is directionally of 1/22/02 MIRU Eunice Well Service. POH w/n Found tbg. stuck @ 3517'. Cut tbg. @	trilled, give subsurface locations and rods & pump. NU BOP. Could not	d measur	ed an true vertical denths for all ma-	rkers and zon	es pertinent to this work \"	
1/23/02 RIH w/4-3/4" cutrite shoe, 2 jts. 4-1/2 pipe up to 3287'. Could not move up	" wash pipe, DC's & 2-7/8" the to	3312'. T	Γbg. stacked out. Would not move.	RU reserve	unit. Circulate hole w/soap	y water. Work
1/24/02 RU Computalog WL. RIH w/chemica DC's & 2-7/8" tbg. Caught fish @ 30 DC's & 1-1/2 jts. 2-7/8" tbg.	al cutters & cut tbg. off @ 3082'. R 182'. Jar fish loose & drug it out all	D WL. 1 the way.	POH w/100 jts. 2-7/8" tbg. LD ½ j . Stood back tbg. & DC's. LD tool	t. RIH w/2-7 s & fish. Fish	/8" overshot, bumper sub, lawas 4-1/2" shoe, 2 jts. 4-1	Bowen jars, /2" wash pipe,
1/25/02 RIH w/4-3/4" string mill (2-3/8" x 4' RIH w/2-7/8" overshot, bumper sub, E & 2-7/8" open end mud jt. w/notched	Sowen jars, DC's & 2-7/8" tbg. Ca	og. Mille ught fish	d f/3285' to 3291'. Fell through. I @ 3490'. Jar fish loose. POH w/tl	RIH & tag fisl og. LD tools	h @ 3490'. POH w/2-7/8" & fish. Fish was 8-1/2 jts.	tbg. LD tools. 2-7/8" tbg., SN
1/26/02 RIH w/4-3/4" string mill (2-3/8" x 4' w/2-7/8" tbg. LD DC's & tools.	PS on nose cone), DC's & 2-7/8" th	og. Mill f	6/3515' to 3524'. Fell through. RII	H & tag PBT	D @ 3878'. Circulate hole	clean. POH
1/29/02 RIH w/2-7/8" tbg. Tbg. @ 3270'. SN		IH w/rod	ls & 1-3/4" x 16' pump. Left well p	umping to Ba	attery "A". RDMO.	
18. I hereby certify that the foregoing is true an	d correct.	******	ACCEPTED FOR D		7	
SIGNED Mary Jo Turner	TITLE Procucti	on Tech	ACCEPTED FOR RI		February 14, 2002	
(This space for Federal or State office use)			FEB 2 8 200	2		
APPROVED BY	TITLE			DATE)		
CONDITIONS OF APPROVAL, IF ANY:			ALEXIS C. SWOBO PETROLEUM ENGIN	DDA		

*See Instruction On Reverse Side

5065 SEB 5 7 8 8: 42

RECEVED