			D ~	1		
Form 9-331 (May 1963)		OF THE INTERIOF	(Other instruction	CATE• on re- 5. LEA NM (Form approv Budget Bures SE DESIGNATION 04175 (b)	au No. 42-R14
	GEOLOG	GICAL SURVEY		🛛 🎢 Ser	111 C ANY/	16
SI	UNDRY NOTICES A	AND REPORTS ON	WELLS	0, IF	TRUCAR, ALLOTTE	B OR IRIDE
(Do not use	and a surface encouncies to de	ill or to deepen or plug back OR PERMIT-" for such propo	to a different reservoir			
<u></u>				7. UN	T AGREEMENT N	AMD -
OIL GAS					-	
2. NAME OF OPERATO					Chalk Bluf	
Humble Oil 3. ADDRESS OF OPER	L & Refining Compa	iny			LL NO.	.1
Box 2100	Hobbs, New Mexico	- 88240			24	
4. LOCATION OF WEL See also space 17	L (Report location clearly and	d in accordance with any Sta	te requirements.*		ELD AND POOL, (R WILDCAT
At surface			7_F		mpire Abo	
2310' FSL	& 1650' FEL, Sec. E/4, Section 17.	, 17, 1-18-5, R =27			SURVEY OR ARE	
NW/4 01 31	1/4, Dection 1/1				-	
14. PERMIT NO.	15. EL	EVATIONS (Show whether DF, RT,	, g R, etc.)		DUNTY OR PARIS	- 1
		3450' DF		EQ	dy	New Mex
16.	Check Approprio	ate Box To Indicate Nati	ure of Notice, Repo	rt, or Other [)ata	
	NOTICE OF INTENTION TO:	:		SUBSEQUENT RE	PORT OF :	· · · · · ·
TEST WATER SH	UT-OFF PULL OR	ALTER CASING	WATER SHUT-OFF	v	REPAIRING	
FRACTURE TREAT	T MULTIPLE	E COMPLETE	FRACTURE TREATME		ALTERING	
SHOOT OR ACIDI			SHOOTING OR ACIDIZ			·
REPAIR WELL (Other)	CHANGE 1		Nors Banas	t results of mul Recompletion R	tiple completion eport and Log f	on Well orm.)
17. DESCRIBE PROPOS	ED OR COMPLETED OPERATIONS k. If well is directionally dri	(Clearly state all pertinent d	etnils, and give pertine	nt dates, includ le vertical depti	ing estimated de	ite of starting rs, and zones p
proposed work	rk.) *	med, give substitute istantia	is and measured and tre			
1. Move	in and rig up col	ntract unit.		·		
2. Kill	ed well with water	C •				2.1401.2
2. Kill 3. Pull	ed well with water ed tubing.	5 •	s. lease crude		onuda 15	013 11 11 11 11 11 11 11 11 11 11 11 11 1
2. Kill 3. Pull 4. Frea	ed well with water ed tubing. kdown and leveled	off with 200 bbl:	N HULUUU BALAM	OT TAVDA	crude, 15 crude.	00#
2. Kill 3. Pull 4. Frea 5. Frac Adon	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 (off with 200 bbls and 5514-5524 with gals. R-3 and 1#	n 40,000 gals. 20-40 sand per ith 100 bbls.	r gal. of of lease (rude. Av	00# erage
2. Kill 3. Pull 4. Frea 5. Frac Adon	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 (off with 200 bbls and 5514-5524 with gals. R-3 and 1#	n 40,000 gals. 20-40 sand per ith 100 bbls.	r gal. of of lease (rude. Av	· · :
2. Kille 3. Pulle 4. Prea 5. Frac Adon Tail inje	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a	off with 200 bbls and 5514-5524 with gals. R-3 and 1#	n 40,000 gals. 20-40 sand per ith 100 bbls.	r gal. of of lease (rude. Av	· · :
2. Kille 3. Pulle 4. Prea 5. Frac Adon Tail inje Hall 6. Rera	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 a ed in with glass ction rate of 35.4 iburton. n tubing.	off with 200 bbls and 5514-5524 with gals. R-3 and 1#	n 40,000 gals. 20-40 sand per ith 100 bbls.	r gal. of of lease (rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35.4 iburton. n tubing. bbed.	r. off with 200 bbl: and 5514-5524 with gals. FR-3 and 1# beads. Flushed w: 4 BPM. Average to	n 40,000 gals. 20-40 sand per ith 100 bbls.	r gal. of of lease (rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35 iburton. in tubing. bed.	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed w: 4 BPM. Average to 1.	20-40 sand pe ith 100 bbls. reating press.	r gal. of of lease of 3300#	rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35.4 iburton. n tubing. bbed.	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed w: 4 BPM. Average to 1.	20-40 sand pe ith 100 bbls. reating press.	r gal. of of lease of 3300#	rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35 iburton. in tubing. bed.	r. off with 200 bbl: and 5514-5524 with gals. FR-3 and 1# beads. Flushed w: 4 BPM. Average to 1. flowing oil well	• Successful.	r gal. of of lease of 3300#	rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35 iburton. in tubing. bed.	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed w: 4 BPM. Average to 1.	• Successful.	r gal. of of lease of 3300#	rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35 iburton. in tubing. bed.	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with 4 BPM. Average to 1. flowing oil well RECEIVE	• Successful.	r gal. of of lease of 3300#	rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35 iburton. in tubing. bed.	r. off with 200 bbl: and 5514-5524 with gals. FR-3 and 1# beads. Flushed w: 4 BPM. Average to 1. flowing oil well	• Successful.	r gal. of of lease of 3300#	rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35 iburton. in tubing. bed.	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with 4 BPM. Average to 4 BPM. Average to 5 Flowing oil well RECEIVE JUL 2 196	4	r gal. of of lease of 3300#	rude. Av	· · :
2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35 iburton. in tubing. bed.	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with 4 BPM. Average to 4 BPM. Average to 1. RECEIVE JUL 2 196	4	r gal. of of lease of 3300#	rude. Av	· · :
 Kille Pulle Preal Frac Adon Tail inje Hall Rera Swab Reco Well 	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35; iburton. In tubing. bed. overed all load oi recompleted as a	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with 4 BPM. Average to 4 BPM. Average to 5 C. E. I.V. JUL 2 196 C. C. C. ARTESIA, DEFIC	4	r gal. of of lease of 3300#	rude. Av	· · :
 Kille Pulle Preal Frac Adon Tail inje Hall Rera Swab Reco Well 	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35 iburton. in tubing. bed.	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with 4 BPM. Average to 4 BPM. Average to 5 I. RECEIVI JUL 2 196. D.C.C. ARTERIA, DEFIC	4	r gal. of of lease of 3300#	The second secon	
 Kille Pulle Preal Frac Adon Tail inje Hall Rera Swab Reco Well 	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35; iburton. In tubing. bed. overed all load oi recompleted as a	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with 4 BPM. Average to 4 BPM. Average to 5 C. E. I.V. JUL 2 196 C. C. C. ARTESIA, DEFIC	4 4	r gal. of of lease of 3300#	rude. Av	
 Kille Pulle Preal Frac Adon Tail inje Hall Rera Swab Reco Well 	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35. iburton. on tubing. obed. overed all load oi recompleted as a	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with 4 BPM. Average to 4 BPM. Average to 5 I. RECEIVI JUL 2 196. D.C.C. ARTERIA, DEFIC	4 4	r gal. of of lease of 3300#	The second secon	
 2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab 8. Reco 9. Well 18. I hereby cerulfy SIGNED This space for former for the space for the s	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35; iburton. In tubing. obed. overed all load oi recompleted as a	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with 4 BPM. Average to 4 BPM. Average to 5 I. RECEIVI JUL 2 196. D.C.C. ARTERIA, DEFIC	4 4	r gal. of of lease of 3300#	The second secon	
 2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab 8. Reco 9. Well 18. I hereby cerulfy SIGNED This space for former for the space for the s	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35. iburton. on tubing. bed. overed all load oi recompleted as a trecompleted as a set for protone use For First once use Y of APPROVAL, IF ANY:	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with beads. Flu	4 4	r gal. of of lease of 3300#	parts 6-1	
 2. Kille 3. Pulle 4. Preal 5. Frac Adon Tail inje Hall 6. Rera 7. Swab 8. Reco 9. Well 18. I hereby ceruif, signed This space for Approved B Conditions JUL	ed well with water ed tubing. kdown and leveled perf. 5478-5490 a ite Mark II, 200 g ed in with glass ction rate of 35; iburton. In tubing. obed. overed all load oi recompleted as a	r. off with 200 bbls and 5514-5524 with gals. FR-3 and 1# beads. Flushed with beads. Flu	4 4	r gal. of of lease of 3300#	parts 6-1	