Sucinit's Copies to Appropriate District Office

State of New Mexico.

Energy, Minerals and Natural Resources Department

Form	C-1	Q3
Revise	ત 1	-1-8

DISTRIC	Π			
P.O. Box	1980,	Hobbe,	NM	88240

OIL CONSERVATION DIVISION P.O. Box 2088

DISTRICT II

Santa Fe. New Mexico 87504-2088

WELL API NO.		
30-0	15-02052	
5. Indicate Type of Lease	₽	

P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE TEE FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. 647
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: Water	State 647 AC 711
OIL GAS OTHER Injection Well	
2. Name of Operator	8. Well No.
SDX RESOURCES, INC.	92 9. Pool name or Wildcat
3. Address of Operator	
P. O. BOX 5061 MIDLAND, TX 79704	Artesia-QN-GR-SA
4. Well Location Unit Letter N : 990 Feet From The South Line and	1650 Feet From The West Line
Section 27 Townsh.p 18S Range 28E	NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3569	
Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
	BSEQUENT REPORT OF:
	ALTERING CASING
PERFORM REMEDIAL WORK 🔼 PLUG AND ABANDON 🔲 REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLII	NG OPNS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLII PULL OR ALTER CASING CASING TEST AND	NG OPNS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLII PULL OR ALTER CASING CASING TEST AND	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed est casing. Depending upon alate cement to surface, and to 2200'. Circulate
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND OTHER: 12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, incomork) SEE RULE 1103. Plan to pull tubing and packer. Run RBP and packer and teresults will either 1) Run 4-1/2" casing to 2270'. Circularill out shoe, run packer and 2-3/8" plastic coated tubing	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed est casing. Depending upon alate cement to surface, ag to 2200'. Circulate status, OR and cap with a 35' cement. 1200'. Perforate 7" casing
COMMENCE DRILLING PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incompleted Special Spec	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed est casing. Depending upon alate cement to surface, ag to 2200'. Circulate status, OR and cap with a 35' cement. 1200'. Perforate 7" casing
CASING TEST AND OTHER: 12 Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, incomork) SEE RULE 1103. Plan to pull tubing and packer. Run RBP and packer and the results will either 1) Run 4-1/2" casing to 2270'. Circularly out shoe, run packer and 2-3/8" plastic coated tubin packer fluid and set packer and return well to injection so Load hole with mud laden fluid. Spot 100' plug 1100-1 at 400' and squeeze from 300' with saxs Class "C" and surface and install dry hole marker.	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed est casing. Depending upon alate cement to surface, ag to 2200'. Circulate status, OR and cap with a 35' cement. 1200'. Perforate 7" casing
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CASING TEST AND COTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incowork) SEE RULE 1103. Plan to pull tubing and packer. Run RBP and packer and the results will either 1) Run 4-1/2" casing to 2270'. Circularill out shoe, run packer and 2-3/8" plastic coated tubin packer fluid and set packer and return well to injection so at 400' and squeeze from 300' with saxs Class "C" and surface and install dry hole marker. Well history: See attached well data sheet.	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed est casing. Depending upon alate cement to surface, ag to 2200'. Circulate status, OR and cap with a 35' cement. 1200'. Perforate 7" casing
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND OTHER: 12 Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, incomplete to the best of my knowledge and belief. Plun to pull tubing and packer. Run RBP and packer and the results will either 1) Run 4-1/2" casing to 2270'. Circularillout shoe, run packer and 2-3/8" plastic coated tubing packer fluid and set packer and return well to injection so at 400' and abandon well as follows: Set CIBP at 2050' at Load hole with mud laden fluid. Spot 100' plug 1100-at 400' and squeeze from 300' with saxs Class "C" and surface and install dry hole marker. Well history: See attached well data sheet. Thereby certification above is true and complete to the best of my knowledge and belief. WICH DRIEG.	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed est casing. Depending upon alate cement to surface, ag to 2200'. Circulate status, OR and cap with a 35' cement. 1200'. Perforate 7" casing and set a 10 sx plug at
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING CASING TEST AND COTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incowork) SEE RULE 1103. Plan to pull tubing and packer. Run RBP and packer and the results will either 1) Run 4-1/2" casing to 2270'. Circularill out shoe, run packer and 2-3/8" plastic coated tubin packer fluid and set packer and return well to injection so at 400' and squeeze from 300' with saxs Class "C" and surface and install dry hole marker. Well history: See attached well data sheet.	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed est casing. Depending upon alate cement to surface, ag to 2200'. Circulate status, OR and cap with a 35' cement. 1200'. Perforate 7" casing and set a 10 sx plug at

(This space for State Use) ORIGINAL STRAIGS BY TIM W. GUM DISTRICT IS ADVISOR

MAR 3 0 1995

AFFROVED BY -

-+	+		LSE LOC API FIE	I NAME State NAME State NAME State N 27-1 # 30-0/. ILD Artesia	8s-28e 5-0203 0-GR-SA	SZSTATUS	Deate o	
			DRI	LL AND CO	IPLETE			
-+ + : :			ORI	G. OP. Ma	lco Resle	r Yates		
: :			SPU	3569 JD DATE 5- 2902	-8-48	COMP. DATE	7-17-48	<u>-</u> -
			TOI	PS:				_
CASING	HOLE	CASING	WT.	DEPTH SET	sks	TOC	+	
	10	8 5/8	28	613	none 100	Pulled	-	
	8	77	20	2720	100			
BOPD PERFS 9 2429-41 BOPD REMEDIA DATE Mhole @ 2425'. casing Fraced	-24 and ,2302-08 L WORK / ay & Jun 224'. I Ran tul had 40# well 4-	BWPD 9-25-56 23 3,2181-2211 BWPD AND WORKOVE 10-75 Sque Drilled cen pinc & pkr.	MCF 72-78,23 ea. int MCF Reze jobs ment to 2 set at	PD	BHP ainer set done voi -7-75 inj	OF 20M/10M.	10-4-56 SO 00sxs. Sqz 2411' to water @ 129 and 750# of	Ed.
	TIENWORK .					3-24-1 coate <u>d - new</u>	30.	
P	 JMP							
	NCHOR				SN on l	bottom		
Pi	ACKER _J	ohnston 10	1-s 7"	Rt. to rel	ease.	8-10-85	2099.52′	_
P	JMPING U	NIT				ID#		
M	OTOR				ID#			
W.	ELLHEAD	_Hinderlit	er	M	ETER # R	ockwell/Will	is choke	
7-9-85	S: Well to 8-10	was deepen	ed Dec.	'70. 1-11 '', 0-60',2	-71 star 20-60′,22 in.	ted inj. wat 5'120-240';.	er @ 2616′ 8-9-85 csg	 L <u>.</u>
nera 4	JOE TOL	J man adı	. coy. a	P.C. DOCK			cilled ev-	stent. at 2