

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-015-02601

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

B-P America Production Co.

3. Address of Operator

P.O. Box 1089 Eunice, N.M. 88231

4. Well Location

Unit Letter H : 1650 feet from the North line and 990 feet from the East line

Section 5 Township 18S Range 28E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

KB = 12

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

T.D. 6351', PBTD 6335', 5 1/2 - 15.5# TAC @ 6222'.

PROCEDURE TO P&A WELL:

- (1) MIRU PU. Check tbg. & csg. press. Blow well down to pit. Kill well w/Brine Water if necessary.
- (2) ND well head & NU BOP & Enviro-vat.
- (3) Release TAC & POH w/200 jts. of 2 3/8 tbg., TAC & SN, PN & Mud Joint,
- (4) RIH w/5 1/2 CIBP on wireline & set @ 6132'. POH w/WL.
- (5) RIH w/ OET & Tag CIBP. Circulate hole w/9.5# salt gel mud.
- (6) Cap CIBP w/25 sxs. cmt.
- (7) PUH w/tbg. & spot 25 sxs. cmt. plug from 3697' to 3597'. Glorieta plug.
- (8) PUH w/tbg. & spot 25 sxs. cmt. plug from 894' to 794'. WOC & Tag. Shoe plug.
- (9) PUH w/tbg. & spot 25 sxs. cmt. plug from 443' to 343'. Yates.
- (10) POH w/ tbg. RU wireline to perf.
- (11) Perf 5 1/2 csg. @ 60'. POH w/WL.
- (12) Circulate 5 1/2 & 8 5/8 csg. w/15 sxs. cmt. to surface.
- (13) Cut off well head & anchors 3' BGL. Clean up location & set dry hole marker.

Notify OCD 24 hrs. prior to any work done

Perf csg @ 894' - set 100' cmt in? out
of csg. 794'-894' - Tag
Perf csg. @ 443' - set 100' cmt in? out
of csg. - 343'-443'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kellie D. Murrish

TITLE

Asst. Admin. Asst.

DATE

12.18.02

Type or print name

Kellie D. Murrish

Telephone No.

505.394.1600

(This space for State use)

APPROVED BY

[Signature]

TITLE

Wild

DATE

DEC 31 2002

Conditions of approval, if any